

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1830' FSL, 1980' FEL, Sec. 6, T-27-N, R-9-W, NMMPM

5. Lease Number
SF-077874

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Hanks #20

9. API Well No.
30-045-11731

10. Field and Pool
So Blanco PC

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☒ Other - Restimulate	

13. Describe Proposed or Completed Operations

5-4-98 MIRU. ND WH. NU BOP. TOOH w/115 jts 1" tbgs. TIH w/4 1/2" RBP, set @ 2300'. Load hole w/35 bbl wtr. PT 4 1/2" csg, failed. TOOH. TIH w/4 1/2" pkr, set @ 1040'. PT RBP & 4 1/2" csg to 3100 psi, OK. PT backside to 2800 psi, failed. Isolate csg leak @ 124-140'. TOOH w/pkr. Dump 5' sd on top of RBP. SDON.

5-5-98 (Verbal approval to squeeze csg from Dwayne Spencer, BLM, Johnny Robinson, OCD Establish circ down csg & out bradenhead. Pump 300 sx Class "G" neat cmt w/3 calcium chloride. Circ 1 bbl cmt to surface. Squeeze to 300 psi. WOC. SDON.

5-6-98 TIH, tag TOC @ 45'. Establish circ. Drill cmt @ 45-137'. Circ hole clean. TOOH Load hole w/3 bbl wtr. PT 4 1/2" csg to 500 psi, bled off to 140 psi/5 min, then held. TIH w/retrieving tool. Blow well & CO. Circ hole clean. Latch RBP TOOH. TIH, tag up @ 2450'. Blow well & CO. SDON.

5-7-98 TIH w/4 1/2" FB pkr, set @ 1198'. Pump 500 gal 15% HCl ahead. Frac existing Pictured Cliffs perms @ 2416-2452' w/473 bbl 20# linear gel, 256,780# 20/40 Brady sd, 481,700 SCF N2. SI for gel break. CO after frac. SDON.

5-8-98 Blow well & CO. Release pkr, TOOH. TIH, blow well & CO.

5-9/10-98 Blow well & CO.

5-11-98 Blow well & CO to PBTD @ 2514'. TOOH. ND BOP. NU WH. RD. Rig released.

5-12/17-98 MIRU. Blow well & CO.

5-18-98 Blow well & CO. (Verbal approval to do casing repair from Wayne Townsend, BLM).

5-19/21-98 Blow well & CO. SD.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 6/11/98

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

ACCEPTED FOR RECORD

Date _____

JUL 20 1998

NMOCD

FARMINGTON DISTRICT OFFICE

5-26-98 MIRU. ND WH. NU BOP. TIH w/4 1/2" RBP, set @ 1186'. Dump 5' sd on top of RBP.
TOOH. TIH, load hole w/6 bbl wtr. Establish circ down csg & out bradenhead.
Pump 12 sx micro matrix cmt @ 140'. TOOH. Sqz 0.25 bbl to 500 psi. TOOH.
WOC. SDON.

5-27-98 WOC.

5-28-98 TIH, tag TOC @ 27'. Establish circ. Drill cmt @ 27-135'. Circ hole clean. TOOH.
TOOH. Load hole w/wtr. PT 4 1/2" csg to 270 psi/15 min, OK. TIH w/retrieving tool.
Circ hole clean. Latch RBP @ 1186', TOOH. TIH, circ hole clean. SDON.

5-29-98 Circ hole clean. SD for weekend.

5-30-98 Circ hole clean. SDON.

5-31-98 Circ hole clean. TOOH. TIH W/75 jts 1 1/2" 2.33# J-55 tbg, landed @ 2426'. ND BOP.
NU WH. RD. Rig released.

