Form 3160-5 (August 1999)

## DEPARTMENT OF THE INTERIOR

**UNITED STATES BUREAU OF LAND MANAGEMENT**  FORM APPROVED OMB NO. 1004-0135

|     | Expires, Novemi                   | per 30, 2000 |
|-----|-----------------------------------|--------------|
|     | Lease Serial No.<br>NMSF - 078390 |              |
| 6 T | Cladian Allaster and Total        |              |

| SUNDRY NOTICES AND REPORTS ON WELLS                           |
|---|
| Do not use this form for proposals to drill or to re-enter an |
| abandoned well. Use form 3160-3 (APD) for such proposals.     |

| abandoned we  | ll. Use form 3160-3 (APE   | or to re-enter and) for such proposals.  | 6. If Indian, Allotte  | ee or Tribe Name  |
|---|--|--|--|---|
| SUBMIT IN TRI   | PLICATE - Other instruc  | tions on reverse side.   | 7. If Unit or CA/A   | greement, Name and/or No.   |
| 1. Type of Well   |  | 1/3  | 8. Well Name and   | No.   |
| 🗌 Oil Well 🛭 Gas Well 🔲 Ott   | her  | 17   | JONES A LS 5   |   |
| 2. Name of Operator BP AMERICA PRODUCTION   | COMPANY Contact:   | MARY CORLEY<br>E-Mail: corleyml@bp.com   | 9. API Well No.<br>30-045-2381   | 2   |
| 3a. Address<br>P.O. BOX 3092<br>HOUSTON, TX 77253   |  | 3b. Phone No. (include area gode<br>Ph: 281.366.4491<br>Fx: 281.366.0700   | 10. Field and Pool.<br>BLANCO MV   | or Exploratory<br>' & PC  |
| 4. Location of Well (Footage, Sec., 7   | ., R., M., or Survey Description)  |  | 11. County or Pari   | sh, and State   |
| Sec 13 T28N R8W SENW 11:  | 20FNL 1815FWL  |  | SAN JUAN C   | COUNTY, NM  |
| 12. CHECK APPI  | ROPRIATE BOX(ES) TO  | INDICATE NATURE OF   | NOTICE, REPORT, OR OTI   | IER DATA  |
| TYPE OF SUBMISSION  |  | ТҮРЕ О   | F ACTION   |   |
| Notice of Intent  | ☐ Acidize  | ☐ Deepen   | ☐ Production (Start/Resume)  | ☐ Water Shut-Off  |
| _   | ☐ Alter Casing   | ☐ Fracture Treat   | □ Reclamation  | □ Well Integrity  |
| ☐ Subsequent Report   | ☐ Casing Repair  | ■ New Construction   | ☐ Recomplete   | Other   |
| ☐ Final Abandonment Notice  | ☐ Change Plans   | ☐ Plug and Abandon   | ☐ Temporarily Abandon  |   |
|   | ☐ Convert to Injection   | ☐ Plug Back  | ■ Water Disposal   | ng  |
| Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f BP America Production Compcompletion to a single string c Mesaverde & Blanco Pictured The Blanco Mesaverde (7231 Commingling per NMOCD On The working, overriding, and r therefore, no notification of this Production is proposed to be a year 2000 from each pool as r Commingling Production Dow value of the total remaining pr | rk will be performed or provide to perations. If the operation resistandomment Notices shall be file inal inspection.)  In any request permission to completion and commingle Cliffs Pools as per the atternation of the proof of the proof of the property of the proof o | he Bond No. on file with BLM/Bl. ults in a multiple completion or rec d only after all requirements, includ convert the subject well fror production downhole from the ached procedure. ffs (72359) Pools are Pre-Ap used commingled pools are is submitted. at age based actual production and a produ | A. Required subsequent reports shall ompletion in a new interval, a Form ding reclamation, have been completed in a dual string ne Blanco opproved for Downhole dentical, an reported in | be filed within 30 days 3160-4 shall be filed once ed, and the operator has |
| 14. I hereby certify that the foregoing is  | Electronic Submission #* For BP AMERICA PRO  | 0448 verified by the BLM Wel<br>DDUCTION COMPANY, sent t   | Il Information System<br>to the Farmington   |   |
| Name (Printed/Typed) MARY CC  | RLEY   | Title AUTHO  | ORIZED REPRESENTATIVE  |   |
| Signature (Excorponic   | My Colly   | Date 02/21/2   | 2002   |   |
|   | Acidize  |  |  |   |
| Approved By /s/ Jin   | n Lovato   | Title Pel  | r. Eng. Dat  | 2/28/02   |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

## Jones A LS #5A Commingle Procedure

## Procedure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. Tag for fill above Model 'D' packer set at 3192' and TOH with 1-1/4" short string currently set at 3031'.
- 6. If fill was detected, TIH and cleanout fill above packer. TOH and LD 1-1/4" production tubing.
- 7. TOH with 2-3/8" production tubing currently set at 5531'.
- 8. Mill slip elements on Model 'D' packer set at 3192' and retrieve packer with packer plucker.
- 9. Tag for fill and, if necessary, cleanout fill to PBTD at 5614'.
- 10. Rabbit tubing and RIH with 2-3/8" production tubing.
- 11. Land 2-3/8" production tubing at 5500'.
- 12. ND BOP's. NU WH. Test well for air. Return well to production and downhole commingle PC and Mesaverde.

| ALLOCATION Based on 2000 Annual Production |     |     |       |     |  |  |  |
|--|-----|-----|-------|-----|--|--|--|
| Formation                                  | BBL | %   | GAS   | %   |  |  |  |
| Mesaverde                                  | 30  | 19% | 71332 | 90% |  |  |  |
| Pictured Cliffs                            | 125 | 81% | 7975  | 10% |  |  |  |