Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT		5. Lease Designation and Serial No. SF78089 CACA
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well  Oil Well  Other		8. Well Name and No.
2. Name of Operator		Scott Federal #16
Bonneville Fuels Corporation  3. Address and Telephone No.		9. API Well No. 3004524550
1660 Lincoln, Suite 1800, Denver, CO 80264 (303) 863-1555  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		W. Kutz Pictured Cliffs
1520' FSL, 1120' FWL Sec 24L T27N R11W		11. County or Parish, State
		San Juan, NM
12. CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
23 Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form 3
Bonneville Fuels Corporation the Fruitland Coal.	requests permission to recomplete the a	above referenced well in
See attached for	recompletion procedure.	6 /2 E
Work to Com	nace granous sumotily	₩ ₩ ₩ ₩
	CERT ST.	1: 22 TOH, N.M.
	OIL ON	
14. I hereby certify that the foregoing is true and forect	Operations Manager	9/01/92 Date
(This space for Federal or State office use)		APPHOVED
Approved by	Title	AS AMENDED
Conditions of approval, if any:		519141992
Title 18 U.S.C. Section 1001, makes it a crime for any person representations as to any matter within its jurisdiction.	n knowingly and willfully to make to any department or agency of the entire	d AMPA WANIAG E Paudulent statements

Scott Federal #16
KB 6251, GL 6247, PBTD 1993
2 7/8" 6.5# csg. @ 2024
Perfs 1904-30,40-56,64-68
46 .34" holes

## Fruitland Coal Recompletion

- 1. Kill well, ND Wellhead, NU BOPs
- Tag Bottom and TOH w/tbg Tallying out
- 3.  $PU^{2}$ " bit, TIH w/ 1 1/2" tbg
- 4. Clean out to bottom
- 5. Run Cement Bond Log
- 6. TOH w/ tbg and bit
- 7. TIH w/ tbg and Arrow type 32 packer
- 8. Set packer @1880KB
- 9. Squeeze perfs w/ ±25 sxs class B CMT and additives, displace through packer
- 10. Perforate and squeeze casing as required by CBL
- 11. PU 2" bit, TIH w/ tbg, drill out to 1916
- 12. Set CIBP @1916
- 13. Pressure up CSG to 500 psi and test squeeze job
- 14. Perforate from 1896-1902 and 1859-63, 4spf
- 15. Breakdown perfs w/ 500 gal 15% HCL and flush with 2% KCL water
- 16. Frac w/ 22,000 gal 70 Q  $N_2$  foam and 40,000 lbs 20/40 sand.
- 17. TIH w/ tbg and bit and Circulate sand out to CIBP
- 18. TOH w/ tbg, set retrivable brigde plug @1800
- 19. Perforate from 1745-49 and 1723-27
- 20. Breakdown perfs w/ 500 gals 15% HCL and flush with 2% KCL
- 21. Frac w/ 19,000 gal 70 Q  $N_2$  foam and 28,000 lbs 20/40 sand.
- 22. TIH w/ tbg and retrieving head
- 23. Circulate sand out to RBP
- 24. Retrieve RBP and TOH w/ tbg and RBP
- 25. TIH w/ 2 3/8" production tbg and BHA, hang off @1840KB
- 26. Swab well on, and test
- 27. Hookup compressor, pipeline and place on line