MANAGE TON HELD OFFICE

Form 3160-5 (November 1994)	UNITED STATE DEPARTMENT OF THE	NTERIOR RIM		OMB No. 1004-0135 Expires July 31, 1996		
BUREAU OF LAND MANAGEMENT				5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS AM			9: 23	SF 078896		
Do not use t abandoned w	his form for proposals to vell. Use Form 3160-3 (AP		ini NM	6. If Indian, Allo	ttee or Tribe Name	
SUBMIT IN TH	RIPLICATE - Other instr		den jar garija.	7. If Unit or CA/	Agreement, Name and/or No.	
1. Type of Well						
Oil Well Gas Well Other			JUN - 1 190 8. Well Name and No. Federal 33-24			
2. Name of Operator	t 1 Car Comp			9 API Well No.		
Louis Dreyfus Na	Coringe Parkway	3b. Phone No. (include pr	a sode	045-2		
3a. Address 14000 Quail Springs Parkway Ste. 600, Oklahoma City, OK 73134 3b. Phone No. (405) 74			DIST 3		l, or Exploratory Area	
4. Location of Well (Footage, Se	c., T., R., M., or Survey Descriptio				uitland Coal	
				11. County or Par	ish, State	
1190' FSL & 1450' FWL Sec. 33-T27N-R11W				l	County, NM	
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATURE	OF NOTICE, R	EPORT, OR O'I	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
77/	Acidize	Deepen [Production (Start	(Resume)	Water Shut-Off	
Notice of Intent	☐ Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	☐ Temporarily Ab	andon		
	Convert to Injection	,	Water Disposal			
Attach the Bond under which following completion of the itesting has been completed.	the work will be performed or provolved operations. If the operations had been shall been also shall be the control of the operation of the op	ovide the Bond No. on file wit on results in a multiple complet be filed only after all requiren	h BLM/BIA. Requi ion or recompletion tents, including recla	red subsequent repo in a new interval, a armation, have been	orts shall be filed within 30 days Form 3160-4 shall be filed once completed, and the operator has	
0 1 (001	3000 psi. Perfora					
1616', 2 spf, 3. RD WL. RU BJ SG ballsealer balls off per and ±2600 psi XL base) and	29 holes. Acidize/balloff s. Estimated rate fs and wait for ba surface treating ±90000# 20/40 Ariz load, swab and/or	Fruitland Coal of 6-8 BPM @ ± 1000 alls to fall below pressure. Pump are cona Sand and 1000	v/1000 gals) psi. Flus w perfs. F: ±50000 gal.	. 15% HCl a sh w/2% KCl rac Fruitla 70 Quality	cid w/87 7/8" 1.3 water. Surge and Coal @ 60 BPM v N2 foam (25#	
5 DI DII /2 2	1011 +ha f alamout	- +△ PRTD ₩/N//.	POOH w/tbg.			
6 PII TA & RTH v	2 3/8" production	tbg. w/productio	n assembly,	set SN @ ±	1650'. PU & RIH	
/3//!! rode 8	: 1 1/4" RHP. ND F	ROP & NU wellhead	. KDMO WOO	•		
7. Build pad & :	install pumping uni	it. Hang Well on	, start uni	t & turn we	=======================================	
14. I hereby certify that the forego Name (Printed/Typed)		Title	Manage Ma - 1 *	ofor		
Telfye D. Diyane			Regulatory Technician Date			
Signature	Gentler P	5/5/99		AMACASS	40	
- Junyum Jo	THIS SPACE	FOR FEDERAL OR STA	TE OFFICE USE		THE WAY	
Approved by		Title		Day	2 1999	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.