

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on the
reverse side.)

Form approved:
Budget Bureau No. 1004-1
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL
BLM # SF-077329
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME K
2. NAME OF OPERATOR McKenzie Methane Corporation	8. FARM OR LEASE NAME Angel Peak 11K
3. ADDRESS OF OPERATOR 1625 Broadway, Suite 2580, Denver, Co. 80202	9. WELL NO. #2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1350' FSL, 1360' FWL SE 1/4 NE 1/4 SW 1/4	10. FIELD AND POOL, OR WILDCAT Basin Fruitland Coal
14. PERMIT NO. API #30-045-27613	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11-T27N-R10W
15. ELEVATIONS (Show whether OF, RT, GR, etc.) GR 6258'	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANE ☐	(Other) ☐	
(Other) Well Status Update ☒		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

SEE ATTACHED WELL HISTORY

RECEIVED
JUN 11 1990
OIL COAL DIV
DET. 2

ACCEPTED FOR RECORD

MAY 30 1990

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Sam Cadz</u>	TITLE <u>Technician</u>	FARMINGTON RESOURCE AREA
(This space for Federal or State office use)		BY <u>[Signature]</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY: NMOCL		

*See Instructions on Reverse Side

4/19/90 TD 2220', PBTD 2175'. MIRUSU, NDWH, NU BOP. RIH w/3-3/4" bit & scraper on 2-3/8" tbg. Tag FC @ 2175'. Roll hole w/FW & POOH & SDON. Prep to rn logs.

4/20/90 Run GR/CCL/CBL fr/PBTD to 1700'. PT csg, no good. Pump 1/2 bpm @ 2700#. RIH w/ pkr & test float clr. Held 4000#. Hunt for csg leak. Locate top of leak @ 416', locate btm of leak @ 815'. PT below leak to 2500#, held OK. Release pkr & POOH, TIH & spot 50 sks (59 cu ft) Class B cmt plug @ 810'. POOH. Displace cmt dwn csg, squeezed to 2500# w/ 2 - 1/2 bbls. displaced. Bled off to 2000# & SWION. Est. top of cmt @ 160' from surface.

4/21/90 RIH w/ 3 - 3/4" bit on 6, 3 - 1/8" drl clrs. Tag cmt @ 200' & drl out to 400'. POOH & SDOW.

4/23/90 RIH w/3-3/4 bit on 10, 3-1/8 DC & 2-3/8 tbg. DO cmt to 815'. Circ hole clean & POOH. PT sqz holes to 1000#. PT no good. SDON.

4/24/90 RIH w/pkr on 2-3/8" tbg. Loc csg lk @ 416' - 447'.TOOH. TIH & spot 1-1/2 bbl Cl B, 2% CaCl cmt (8.5 cu. ft.) @ 447'. Pull 2 stands & rev tbg clean POOH. Sqz lk dwn csg. Displ 1/4 bbl & sqz to 2000#. SWION.

4/25/90 RIH w/3-1/4" bit & 10, 3-1/8" DC. Tag cmt @ 335'. Drl cmt to 450', circ hole clean & POOH. PT csg to 1000#, held OK. TIH w/DC & TOOH LD same. RIH to PBTD w/bit & scraper. POOH. Perf lwr coals w/3-1/8" csg gun, 16 gram charges, 2 SPF, fr 2093-98 & 2122-38. TIH w/spit tl & acd perfs as follows w/2.5 bbls 15% HCL per set:

Perfs	Rate	Pressure	ISIP
2132-2138	1.2 bpm	150	N/A
2128-2132	1.3 bpm	450	200#
2122-2128	1.0 bpm	450	200#
2093-2098	1.8 bpm	850#	250#

Rel spit tl & POOH, RIH w/68 jts 2-3/8" tbg w/SN on btm. Land tbg @ 2128'. NDBOP & NUWH. Kick well around w/N2. Flow well to pit to clean up. SDON.

Note: BJ - Service Co., Husky - Wireline.

4/26/90 Tbg dead, CP 175#. Md 1 swb rn & kicked well off, well flwg sli. Wait 1 hr & swb. Rec no fl, wait 1 hr & swb. Rec 2 BW. FCP @ 75#. Well flwg sli. Flwg well to clean up. RDMOSU.

5/18/90 PBTD 2175', TD 2220', mk swb rn. MIRU Triple P #1. Mk swb rn rec 300'fl. Next rn dry. Well flwg 10-15 min. SDON.

5/19/90 Well op to pit. Mk 1 swb rn. Well dry. RDMOSU.