

## United States Department of the Interior



BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401

(N REPLY REFER TO SF-078357-A et al. (WC) 3162.3-1 (019)

OCT. 1 8 1991

Texaco Inc. 3300 N. Butler Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 4 J. Q. Marshall, sec. 1, T. 27 N., R. 9 W., San Juan County, NM, lease SF-078357-A.
- y2. 4 H. J. Loe Federal B, sec. 23, T. 29 N., R. 12 W., San Juan County, NM, lease NM-014378.
- 3. 8 Nellie Platero, sec. 10, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8464.
- 4. 10 John Charles, sec. 13, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8466.
- 5. 5 Charley Pah, sec. 12, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8465.
  - $\sqrt{6}$ . 3 Neah Victoria, sec. 1, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8463.

As discussed with Mark Wakefield of your company on, October 11, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.


Sincerely,

John L. Keller Chief, Branch of Mineral Resources

6 Enclosures

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410 BIA, Window Rock

ABANDONED LOCATION



OIL CON. DIV \DIST.3

