



LTR



Job separation sheet



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO

SF-078094 et al. (WC)
3162.3-1.0 (019)

NOV. 1 4 1991

RECEIVED
NOV 15 1991
OIL CON. DIV.
DIST. 2

Bonneville Fuels Corporation
1600 Broadway, Suite 1110
Denver, Co. 80202

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. No. 14-14 Fullerton Federal, Sec. 14, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078094.
2. No. 36-23 Scott E Federal, Sec. 36, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.
3. No. 24-23 Scott E Federal, Sec. 24, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.
4. No. 13-14 Fullerton Federal, Sec. 13, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078094.
5. No. 24-12 Scott E Federal, Sec. 24, T. 27 N., R. 11 W., San Juan County, New Mexico, lease SF-078089.

As discussed with Doris Moly of your company on, October 16, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

5 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION