

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT WASHINGTON, D.C. 20250		Form Approved GSA Gen. Reg. No. 42-R1424 U.S. GOVERNMENT PRINTING OFFICE: 1964 O - 354-100
1. WELL IDENTIFICATION (a) NAME OF WELL (b) LOCATION (T, R, S, or BLK. AND SURVEY OR AREA) (c) DATE OF COMPLETION (d) WELL NO.		2. LEASE DESIGNATION AND SERIAL NO. 3. UNIT AGREEMENT NAME 4. PERM OR LEASE NAME 5. WELL NO.
6. FIELD AND POOL, OR WILDCAT 7. SEC., T., R., S., OR BLK. AND SURVEY OR AREA 8. COUNTY OR PARISH 9. STATE		10. FIELD AND POOL, OR WILDCAT 11. SEC., T., R., S., OR BLK. AND SURVEY OR AREA 12. COUNTY OR PARISH 13. STATE
14. ELEVATIONS (Show whether BS, RT, GS, etc.) 15. ELEVATIONS (Show whether BS, RT, GS, etc.)		16. FIELD AND POOL, OR WILDCAT 17. SEC., T., R., S., OR BLK. AND SURVEY OR AREA 18. COUNTY OR PARISH 19. STATE

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

WATER SHUT-OFF	☐	PUMP OR ALTER CASING	☐
FRACTURE TREATMENT	☐	MULTIPLE COMPLETION	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIRING WELL	☐	ALTERING CASING	☐
OTHER	☐	ABANDONMENT*	☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other)	☐		

(Note: Report results of multiple completion on Well Completion or Abandonment Report and Log form.)

20. If well is abandoned, give location clearly and in accordance with any State requirements. (See instructions on reverse side.)

On 7/23/67. Run log to 4800'. Sped 100 sack cement plug on bottom. Pulled tubing and spotted 25 sack cement plug at surface. Released log 7/22/67. Well P&A 7/22/67. Set Dry Hole Marker.



21. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE _____
 (This space for Federal or State office use)

DATE July 31, 1967

APPROVED BY _____
 CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See instructions on Reverse Side