Feb. 1	961)	•	
	- -		
	r		

CURMIT	IN	TRIPLICATE
COUDMII	117	INITUIONIE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Ã	pproval expires	12-31- 60.
Land Offic	Santa 1	e
Lease No.	277107	
	fichener	** A **

GEOLOGICAL SURVEY	
	TO BURELY B

NOTICE OF INTENTI	ON TO DRILL		CIBCEVIENT	REPORT OF WATER SI	UIT-OFF	
	ON TO CHANGE PLANS			REPORT OF SHOOTING		
	ON TO TEST WATER S		l ii	REPORT OF ALTERING		
NOTICE OF INTENTI	ON TO RE-DRILL OR I	REPAIR WELL	1 1	REPORT OF RE-DRILL		
NOTICE OF INTENTI	ON TO SHOOT OR ACI	IDIZE	SUBSEQUENT	REPORT OF ABANDON	MENT	X
NOTICE OF INTENTI	ON TO PULL OR ALIE	R CASING	SUPPLEMENT	ARY WELL HISTORY		
NOTICE OF INTENTIO	ON TO ABANDON WELL	L				
	(INDICATE A	BOVE BY CHECK MA	ARK NATURE OF REPOR		•	
				November 3	,	, 19
		_	om N line and		$1 \left\{ \frac{\mathbf{E}}{\mathbf{X} \mathbf{A}} \right\}$ line of sec	. 33
.E. Section	33	23-N (Twp.)	9⊷₩ (Range)	N.M.P.M.		
	ec. 140.)		-	(Meridian)	w Mexico	
ekota (Field)		(Conn	n Juan ty or Subdivision)		State or Territory)	
ate names of and e	xpected depths to obj	ective sands; show	'AILS OF WOR sizes, weights, and len all other important pro	gths of proposed casin	gs; indicate mudding	jobs, cement-
		ective sands; show ing points, and a	sizes, weights, and len	gths of proposed casin posed work)		jobs, cement-
This well was . Set 75 sk l. Set 25 sk l. Set 25 sk l. Set 75 sk	s Plugged and coment pluged coment co	ective sands; show ing points; and a ad. Abandone ag from 725 ag from 570 ag from 5370 ag from 510	raizes, weights, and lenall other important products of the following to 7578. To 6300.	gths of proposed casin posed work)	L per NO	CEIVE VI U 191 CON. C
his well was. Set 75 sk. Set 25 sk. Set 75 sk. Set 75 sk. Bolt or warker.	as Plugged and comment plug comment plug comment plug comment plug comment plug comment plug cold a plate	ective sands; show ing points; and a defined and Abandone ag from 725 ag from 5370 ag from 5370 over casin	raizes, weights, and len all other important product of the following to 6300'. To 6300'. To 6470'. To 5400'. To 5400'. To flange and	gths of proposed casin posed work) Cwing manner erect a 4 x	Perations may be com	CEIVE V1 U 191 CON. C CAST. 3
his well was. Set 75 sk. Set 25 sk. Set 75 sk. Bolt or warker.	s Plugged and comment pluge comment pluge comment pluge comment pluge de plate	ective sands; show ing points; and a defined and Abandone ag from 725 g from 5370 g from 510 over casin	raizes, weights, and len all other important product of the following to 6300'. To 6300'. To 6470'. To 5400'. To 5400'. To flange and	gths of proposed casin posed work) Cwing manner erect a 4 x	Perations may be com	CEIVE V1 U 191 CON. C CAST. 3
his well was Set 75 sk Set 25 sk Set 75 sk Bolt or w marker.	s Plugged and comment plugic comment	ective sands; show ing points; and a defined and Abandone ag from 725 g from 5370 g from 510 over casin	raizes, weights, and len all other important product of the following to 7578. To to 6870. To 5800. To 5800. To 5800. To 5800.	ghs of proposed casin posed work)	perations may be com	CEIVE V1 U 19 CON. C CAST. 3