Form 2160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED /
OMB NO. 1004-0135/ Expires: November 30,/2000
Expires: November 30, 2000

5 Lease Serial No.

ν.	Douge Derial 1101	
	SF 077085	

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

6.	If Indian,	Allottee or	Tribe	Name

		/* *·	11011 000			
SUBMIT IN TRIP	PLICATE - Other instruc	ctions on reve	rse side: 2001		7. If Unit or CA/Agro	eement, Name and/or No.
1. Type of Well	<u> </u>	92.000.04 84.00		8. Well Name and No. OMLER 7		
☐ Oil Well ☑ Gas Well ☐ Other 2. Name of Operator CONOCO INC.		DEBORAH MARBERRY E-Mail: deborah moore@conoco.com		com	9. API Well No. 30-045-07149	
3a. Address P. O. BOX 2197, DU 3084 HOUSTON, TX 77252-2197		3b. Phone No. (include area code) Ph: 281.293.1005 Fx: 281.293.5090			10. Field and Pool, or Exploratory BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Descriptio	n)			11. County or Parish	, and State
Sec 26 T28N R10W NWSE				SAN JUAN CC	DUNTY, NM	
12. CHECK APPR	OPRIATE BOX(ES) TO	O INDICATE	NATURE OF N	OTICE, R	EPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION		
	☐ Acidize	□ Deep	en	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing		ure Treat	— Reclan	nation	☐ Well Integrity
Subsequent Report	☐ Casing Repair	_	Construction	☐ Recom	plete	☐ Other
	☐ Change Plans		and Abandon		rarily Abandon	
☐ Final Abandonment Notice	☐ Convert to Injection			☐ Water	•	
Conoco Inc. plugged this well	according to the attache	ed summary.				
14. I hereby certify that the foregoing i	Electronic Submission	NOCO INC si	ent to the Farmin ing by Lucy Bee	gton on 11/01/20	001 ()	
Name (Printed/Typed) DEBORA	H MARBERRY		Title REGUL	ATORY A	VALYST	
Signature (Electronic	Submission)		Date 10/31/2	001		
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE (JSE	
						_
Approved By			Title		Date	
Conditions of approval, if any, are attach certify that the applicant holds legal or ewhich would entitle the applicant to conditions.	quitable title to those rights in duct operations the reon.	the subject lease	Office			
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulent	3 U.S.C. Section 1212, make t statements or representations	it a crime for any s as to any matter	person knowingly a within its jurisdiction	nd willfully t n.	o make to any departme	ent or agency of the United

MMOCE

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Conoco Inc.

September 30, 2001 Page 1 of 1

Omler #7 1650' FSL & 1650' FEL, Section 25, T-28-N, R-10-W

Plug & Abandonment Report

San Juan County, NM SF-077085 API 30-045-07149

Cementing Summary:

Plug #1 with CIBP at 1644', spot 15 sxs cement inside casing from 1644' to 1282' to isolate Fruitland Coal perforations.

Plug #2 with 17 sxs cement inside casing from 1001' to 591' to cover Kirtland and Ojo Alamo tops.

Plug #3 with 80 sxs cement pumped down the 3-1/2" casing from 207' to surface, circulation good cement out bradenhead.

Plugging Summary:

Notified JAT on 9/04/01

- 09-10 Road rig toward location, rig repair. SDFD.
- MOL. Held JSA. RU rig and equipment. Layout relief line to pit. Blow down 30# tubing pressure and 70# casing pressure. Pressure test tubing to 500# for 5 min, held OK. Remove stuffing box and unseat pump. LD 1- 8' pup, 68 5/8" rods, 1 20' sinker bar, 1 bottom hole down pump and 1 –16' mud anchor. ND wellhead and NU BOP, test. Changeover to 2-1/16" tools. PU on tubing and LD 1 joint and 2 –10' subs. TOH and tally 25 stands 2-1/16' tubing and LD 4 joints, SN, and 20' mud anchor. Total 55 joints 2-1/16" tubing. Shut in well. SDFD.
- Held JSA. RU A-Plus wireline truck and set 3-1/2" PlugWell CIBP at 1644'. TIH with tubing and tag CIBP at 1644'. Load casing and circulate clean with 20 bbls water. Pressure test casing to 500# for 5 min, held OK. Plug #1 with CIBP at 1644', spot 15 sxs cement inside casing from 1644' to 1282' to isolate Fruitland Coal perforations. PUH to 1001'. Procedure change on plug #2 approved C. Snyder, BLM. Plug #2 with 17 sxs cement inside casing from 1001' to 591' to cover Kirtland and Ojo Alamo tops. TOH and LD tubing. Perforate 3 bi-wire squeeze holes at 207'. Establish circulation out bradenhead with 10 bbls, no circulation out 5-1/2" annulus. Plug #3 with 80 sxs cement pumped down the 3-1/2" casing from 207' to surface, circulation good cement out bradenhead. RD floor and ND BOP. S. McFadden with Conoco issued Hot Work Permit. Dig out and cut off wellhead. Found cement down 6' in casing and annulus. Mix 16 sxs cement to fill casing and then install P&A marker.
 C. Snyder with BLM on location.
- 09-13 Held JSA. RD and MOL.