

well file

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC
87410

June 18, 1974

I. R. TRUJILLO
CHAIRMAN

LAND COMMISSIONER
ALEX J. ARMJO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

Mr. L. O Van Ryan
El Paso Natural Gas Co.
P. O. Box 990
Farmington, New Mexico

Re: Packer leaks

Dear Mr. Van Ryan:

The below listed wells which failed to prove zone separation during packer tests apparently have not been repaired.

Rincon Unit #127, A-28-27N-6W. Tested October, 1973. Filed March, 1974.
Notice to repair dated March 14, 1974. No apparent action to date.

San Juan 28-7 Unit #109, A-18-27N-7W. Tested October, 1973. Filed March 1, 1974. Notice to repair dated March 14, 1974. intent to set blind choke in Dakota tubing filed April, 1974. No apparent action to date.

→ Warren A #2, A-23-28N-9W. Tested March, 1974. Filed April, 1974.
Notice to repair dated April 22, 1974. No apparent action to date.

Ludwick #11, B-19-30N-10W. Tested March, 1974. Filed March, 1974.
Notice to repair dated March 29, 1974. No apparent action to date.

A case will be filed before the Commission on July 8, 1974, to allow The El Paso Natural Gas Company to appear and show why any of these wells, which have not been or are not at that time being repaired, should not be converted to single-zone completions or plugged and abandoned.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Engineer, District #3

ARK:mc

cc: Oil Conservation Commission
Santa Fe, New Mexico