

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

047017 B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Angel Peak B

9. WELL NO.

#16-B

10. FIELD AND POOL, OR WILDCAT

Fulcher Kutz Picture Cliff

11. SEC., T., R., M., OR SLM. AND
SURVEY OR AREA

Section 13-28N-11W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Chaparral Oil & Gas Company

3. ADDRESS OF OPERATOR

Box B, Aztec, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

Section 13-28N-11W

990 ft. from S. line, 990 ft. from E. line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spot cement plug from 1920' to 1800'. Plug to be minimum 50' inside of casing.
2. Spot cement plug across Ojo Alamo Formation from 900' - 1000'.
3. Spot 5 sz plug in surface, install dry hole marker, clean location, and abandon.

(Formerly operated by
Southern Union Prod. Co.)

RECEIVED

FEB 9 1970

GEOLOGICAL SURVEY

RECEIVED

FEB 10 1970

CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED W. Eugene Linder

TITLE President

DATE February 9, 1970

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE