

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved,  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Aztec Oil & Gas Company	8. FARM OR LEASE NAME Reid
3. ADDRESS OF OPERATOR P. O. Drawer 570, Farmington, New Mexico	9. WELL NO. #18
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FNL and 1650' FWL Section 18-28N-9W	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5744 GR
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 18-28N-9W
	12. COUNTY OR PARISH San Juan
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input checked="" type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	


(Other) \_\_\_\_\_

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

PROPOSE TO:

1. Pull tubing.
2. Set Bridge Plug at 6420'.
3. Set Bridge Plug at 6350', Squeeze perf 6322-32'.
4. Run Corrosion Bond Log.
5. Test casing to 2500#.
6. Clean out to top of Bridge Plug at 6420' with gas.
7. Gas frac with Dowell gas frac 3.
8. Rerun 2-3/8 tubing.



18. I hereby certify that the foregoing is true and correct

SIGNED Joe. C. Salmon TITLE District Superintendent DATE October 18, 1971

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: