

## STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

October 28, 1983

Mr. James Smith Southland Royalty Co. Drawer 570 Farmington, NM 87499

Re: Reid A #1 A-13-29N-10W Reid #19 B-18-28N-9W

Dear Smitty:

The attached Packer Tests for the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut both zones in for a minimum of three days and blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop.

Please advise this office at least 24 hours prior to the tests so we may provide a witness.

If you have any questions, please contact me.

Yours truly,

Charles Gholson

Deputy Oil and Gas Inspector

CG/ca

cc: Well files