

CONCESSION SURVEY

SURVEY NOTICE AND REPORT OF WORK

Do not use this form for a permit to drill or to conduct operations on an oil and gas lease. Use "APPLICATION FOR PERMIT" (B-100) for that purpose.

1. Name of Operator <u>Amoco Oil & Gas Company</u>	7. UNIT ADMINISTRATION <u>McClendon</u>
2. Address of Operator <u>P. O. Drawer 570, Fort Worth, Texas</u>	8. Well No. <u>#18</u>
3. Name of Surveyor <u>Blanco, Mesaverde</u>	9. Name and Address of Lessee <u>Blanco, Mesaverde</u>
4. Section, Range, Township, and in accordance with any State Requirements. <u>Section 13-20N-10W</u>	10. County of Survey <u>San Juan</u>
5. Section No. <u>13-20N-10W</u>	11. State of Survey <u>New Mexico</u>



12. Check appropriate box to indicate nature of work, drilling or other data.

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
DRILLING SHUT-OFF	PERMITS TO ALTER CASING	WELLS SHUT-OFF	REPAIRING WELLS
PERMITS TO ALTER CASING	REPAIRING CASING	PERMITS TO ALTER CASING	REPAIRING CASING
PERMITS TO ALTER CASING	REPAIRING CASING	PERMITS TO ALTER CASING	REPAIRING CASING
PERMITS TO ALTER CASING	REPAIRING CASING	PERMITS TO ALTER CASING	REPAIRING CASING

13. Give location and name of well, and give pertinent data, including estimated date of drilling and completion, and, if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and well logs.

WORK TO:

1. Set Bridge Plug at approximately 6100'.
2. Run Bond and Corrosion Log.
3. Perforate and Frac the Points Lookout.
4. Set Production Packer at approximately 6100'.
5. Complete as a Mesaverde/Dakota dual.



1/2 Section 13-20N-10W Dedicated acres 320

14. Signature of Surveyor: [Signature] Date: February 1, 1972

15. Signature of District Superintendent: [Signature] Date: February 1, 1972

16. Signature of Approver: [Signature] Date: [Date]