
Form	9-381 a
(Feb	. 1961)



(SUBMIT IN TRIPLICATE)

Land Office SF		
Lease No. 046563		
Unit	K	

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL	XX
(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)
	·
	November 23, 1960 , 19
STOO Mude Fadamas	7
Well No. 12 22 is located among ft from	(E) to
SI CO Kutz Federal Well No. 13-33 is located 1760 ft. from	S line and 1700. It. from W line of see. 33
sw/A Sec 22 Tree v	" COENT
W/4 Sec. and Sec. No.) Two N	Ringo Of TIVID
Angel Peak Dakota San	Juan County New Jexico Subdivision) (States Torrison 2 2 106)
(Field) (County or	Subdivision) (State or Territors) O 1060
	NUV ZG 1500
The elevation of the derrick floor above sea leve	el is 6418. ft. 6118 OIL CON. COM.
	S OF WORK
	or works
ing points, and all oth	s, weights, and lengths of proposed casings; indicate mudding jobs, coment-
The second secon	% MG (A. CMC. w/ 170
	7/8" " 170 " Disp.
Stage Cement tool at 2212	" 150 " " # #
Suited at 4200 and printing	with a total of 300 sx cement. Last
w/ 3000 psi, Held ok.	with a total of 500 sx cement. Last 7' cmt in pipe. Drilled out and test
4) Attid to sand from w/ see	
2% Ell tubing and analysis	000 # sand and 100,000 gal water thru
sand. Cleaned out to 6680.	t at $6452S$ ereened out with $20,000#$
5) Ran and eat Poken Dear	
2"Fil tail nine to 4800 guil	er at 6542 on 25 EU tubing, with
tial test.	er at 6542 on 25 EU tubing, with well in and prep for Initial Poten-
Tombon total and a	
I understand that this plan of work must receive approval in wr	iting by the Geological Survey before operations may be commenced.
Company Sunset International Pater	coleum Corp.
Address 5 th Floor, Midland Savin	one District
	As prad.
444- 17th Street	By Thos. F. Popp Title District Engineer
	Dy Thomas + follo
Denver 2, Colo.	Title Dietmine Tari
	Title District Engineer

al **fil**a de la fila de la composición del composición de la compo

ing the second of the second o

, r -

.

.

The state of the s

at the second second second second second

and the second of the second o

..

. ...