UNITED STATES

DEPARTMENT OF THE INTERIOR

	Sundry Not	cices and Reports on W	ells	
		Ç. A. A. A.	•, ' .	5. Lease Number SF-030724A
1. Type of We GAS	11			6. If Indian, All. o
2 25 0				7. Unit Agreement Na
2. Name of Ope				
RESO	$URCES^N_{ m ort}$	& GAS COMPANY		
			<u>i_</u> 2	3. Well Name & Numbe
	Phone No. of Opera			Zach::y #42
PO Box 428	89, Farmington, NM	1 87499 (505) 326-9700		API Well No.
1. Location of	f Well, Footage, S	Sec., T. R. M		30-045-25488 10. Field and Pool
		2. 10, T-28-N, R-10-W,		Armenta Gallup
			;	11. County and State
				San Juan Co, NM
2. CHECK APPI	ROPRIATE BOX TO IN	DICATE NATURE OF NOTIC	CE, REPORT, OTI	HER DATA
Type of Sub	bmission	Type of A		
Not	tice of Intent		Change of	
		Recompletion	New Consti	cuction
v cuk	agamiant Danamt			
X Sub	bsequent Report	Plugging Back	Non-Routin	ne Fracturing
	nal Abandonment	Plugging Back Casing Repair	Water Shut	ne Fracturing c off
		Plugging Back	Water Shut	ne Fracturing c off
Fir	nal Abandonment	Plugging Back Casing Repair Altering Casing _X_ Other - Tubing 1	Water Shut	ne Fracturing c off
Fir		Plugging Back Casing Repair Altering Casing _X_ Other - Tubing 1	Water Shut	ne Fracturing c off
Fir	mal Abandonment Proposed or Comp MIRU. TOOH w/rod rods & 2 3/8" t	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	mal Abandonment Proposed or Comp MIRU. TOOH w/rod rods & 2 3/8" t	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. Ti	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir 3. Describe 1-29-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir 3. Describe 1-29-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Fir 3. Describe 1-29-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. The Casing SD for wknd.	Water Shut Conversion repair TH to PBTD @ 60	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Tir 3. Describe 1-29-99 2-2-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3 released.	Plugging Back Casing Repair Altering Casing X Other - Tubing releted Operations ds. ND WH. NU BOP. Tibg. SD for wknd. 3/8" 4.7# J-55 tbg, set	Water Shut Conversion repair TH to PBTD @ 60° @ 5997'. ND Bo	ne Fracturing c off n to Injection 70'. TOOH w/remaining
Tir 3. Describe 1-29-99 2-2-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3 released.	Plugging BackCasing RepairAltering Casing _X_Other - Tubing releted Operations ds. ND WH. NU BOP. Tracks. SD for wknd. 3/8" 4.7# J-55 tbg, set	Water Shut Conversion repair TH to PBTD @ 60' @ 5997'. ND Bo	ne Fracturing c off n to Injection 70'. TOOH w/remaining OP. NU WH. RD. Rig
Jescribe 1-29-99 2-2-99	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3 released.	Plugging BackCasing RepairAltering Casing _XOther - Tubing releted Operations ds. ND WH. NU BOP. The Color of the State of the St	Water Shut Conversion repair TH to PBTD @ 60' @ 5997'. ND Bo	ne Fracturing c off n to Injection 70'. TOOH w/remaining OP. NU WH. RD. Rig
Jescribe 1-29-99 2-2-99 This space fo	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3 released.	Plugging BackCasing RepairAltering Casing _XOther - Tubing releted Operations ds. ND WH. NU BOP. The Color of the State of the St	Water Shut Conversion repair TH to PBTD @ 60' @ 5997'. ND Bo	ne Fracturing c off n to Injection 70'. TOOH w/remaining OP. NU WH. RD. Rig
J-29-99 2-2-99 This space for PPROVED BY	MIRU. TOOH w/rod rods & 2 3/8" to TIH w/190 jts 2 3 released.	Plugging BackCasing RepairAltering Casing _XOther - Tubing releted Operations ds. ND WH. NU BOP. The Color of the State of the St	Water Shut Conversion repair TH to PBTD @ 60' @ 5997'. ND Bo	ne Fracturing c off n to Injection 70'. TOOH w/remaining OP. NU WH. RD. Rig