

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WDW	5. LEASE DESIGNATION AND SERIAL NO. I-89-Ind-57
2. NAME OF OPERATOR John Staver	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo tribal 3-045-06963
3. ADDRESS OF OPERATOR % Pohlmann & Assoc, Room 200 Petr. Plaza 3535 E. 30th, Farmington, NM 87401	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 625' FSL & 1980' FEL sec. 34	8. FARM OR LEASE NAME Table Mesa
14. PERMIT NO. NOV 21 1986	9. WELL NO. 23
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5334 GL	10. FIELD AND POOL, OR WILDCAT Table Mesa Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 34, T28N, R17W
	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged & Abandoned as follows:

1. Spot 15 sack cement plug from TD 1400' to 1280'.
2. Spot 10 sack cement plug from 500' to 600'.
3. Spot 5 sack cement plug from surface (50') with regulation marker.
4. Clean and restore location.

Approved as to
Liability under the
surface restoration to the

OIL CON. DIV.)
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE 11-20-86

DATE

John S. Keller

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side