UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) **UNITED STATES**

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

	1-149-IND-84//					
SUNDRY NO	OTICES AND REPORTS Croposals to drill or to deepen or plug b	ON WELLS tack to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE MAME			
1.	7. UNIT AGREEMENT NAME					
OIL WELL OTHER 2. NAME OF OPERATOR Clinton Oil Company 3. ADDRESS OF OPERATOR P. O. Box 3280, Casper, Wyoming 82601 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			Gallegos Canyon Unit N.1 8. FARM OR LEASE NAME 9. WELL NO.			
				140 10. FIELD AND POOL, OR WILDCAT Cha Cha Gallup 11. SEC., T., B., M., OR BLK. AND		
				1915' FSL, 2070	' FWL, Sec. 29, T281	N, Rl2W
			14. PERMIT NO.	15. ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
71. 12hm12 ho	5555' G.L.	, , , , , , , , , , , , , , , , , , , ,	San Juan New Mexico			
	Appropriate Box To Indicate N					
NOTICE OF I	NTENTION TO:	SUBS	EQUENT REPORT OF:			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL			
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING			
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* X			
REPAIR WELL	CHANGE PLANS	(Other)(Note: Report resu	ilts of multiple completion on Well			
(Other)	o openation of Allegely state all portions	t datails and give pertinent dat	mpletion Report and Log form.) es, including estimated date of starting any			
proposed work. If well is di nent to this work.) *	rectionally drilled, give subsurface local	tions and measured and true ver	tical depths for all markers and zones perti-			
Summary of Opera						
	8 5/8" @ 135' Cemer					
	g: 4 1/2" @ 5300' ·	- cemented with	2 stages			
Gallup perfs: 5	203 5211.					
Spotted 15 sks c	ement plug 5075' to	4885'				
	ement plug 4126 to					
Shot and nulled						
Spotted 30 sks co	ement plug 890' to	870' (across cas	ing stub) 55			
Spotted 30 sks co	ement plug 30' to 1	85' (across surf	ace casing shoe			
Set 10 sks in su	rface pipe.	•				
Space between pl	ement plug 890' to sement plug 30' to large pipe. ugs filled with mud	laden fluid				
Cut off casing he	ead, welded plate be	elow G.L.				
Thoroughly clean	ed up location.	<i>Y</i>	A Committee Comm			
		-				
			MAR 1 3 1975			
		<u>;</u>). 9. 6 00 (1000) (500) (50) (4. 04.05 (1000) (5			
18. I hereby certify that the forego	ing is true and correct Pro	oduction Enginee	r			
SIGNED Temp 1/C			trict DATE March 10, 1975			
(This space for Federal or Stat	e office use)					
•			5.177			
APPROVED BYCONDITIONS OF APPROVAL,			DATE			