

Inspected 9-20-57 O.K. SLPBudget Bureau No. 42-R358.4  
Approved by W. A. Poe

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No. 020499

Unit

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 23rd,

37

19

Well No. 1 is located 1630 ft. from 440 <sup>(N)</sup><sub>(S)</sub> line and 1300 ft. from 4E <sup>(E)</sup><sub>(W)</sub> line of sec. 22  
30N 11W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Rutan Canyon San Juan County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5538.6 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned above well July 23, 1957. Cemented with 300 sacks regular cement first stage. Let set 8 hrs, went in hole found top of plug at 330' from top of hole. Ran second stage cement with 150 sacks regular cement to surface. Hole full of cement from top to TD 1630'.

Will set well marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Ohio Oil CompanyAddress P.O. Box 948, Durango, Colo.By W. A. PoeTitle Production Foreman

