Form 3160-5 (June 1390)...

Conditions of approval, if any:

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU OF LAND	MANAGEMENT	Expires: March et, 1000
SUNDRY NOTICES AND Do not use this form for proposals to drill or to Use "APPLICATION FOR PER	deepen or reentry to a different reservoir.	Essee Designation and Serial No. SF-078828 If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oli Gee Well Well Other		8, Well Name and No.
2. Name of Operator	Attention:	Gallegos Canyon Unit 67
Amoco Production Company 3. Address and Telephone No.	Pat Archuleta	3004507359
P.O. Box 800, Denver, Colorado 80201	(303) 830-5217	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Fruitland Coal
1150'FNL 1650'FEL Sec	c. 22 T 28N R 12W Unit B	11. County or Perish, State San Juan New Mexico
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, F	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water Dispose of multiple completion on Well Completion or other Report and Log form.
Describe Proposed or Completed Operations (Clearly state all pertiner subsurface locations and measured and true vertical depths for all management of the Production Company requests permis recomplete to the Fruitland Sand.		
If you have any questions contact Dave Smit	th at (303) 830-4502.	
14. I hereby certify that the foregoing is true and correct Signed Chicketa	Title Staff As	sst. Date 11-11-1996
This space for Federal or State office use)		PPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United STE

GCU #67 Sec. 22 T 28 R 12 Completed 3/54 PBTD=1544'

- 1. Check location for anchors. Install if necessary. Check anchors.
- 2. MIRUSU. Blow down well.
- 3. Lower tbg and tag CIBP at 1544'. Tally out of hole with 2 3/8" tbg and lay down.
- 4. RIH with 2 3/8" workstring and cement retainer. Set retainer at 1444'. Test casing integrity to 500#. Run GR/CCL. Correlate with cased hole logs dated 8/93 (no original logs are available for this well).
- 5. Squeeze Fruitland Coal perfs at 1528'-1540' with 60 cu ft. cement + 20 cu ft. cement to allow a 100' plug above the CIBP (1544'-1444'). Pull out of retainer.
- 6. RIH with casing gun and perforate Fruitland sand at 1256'-1264' at 2 spf. Break down perfs and look for gas blow. If fair to good gas blow is detected after breakdown, attempt to flow test trough a 1/4"choke for 24 hours. Report findings to Denver.
- 7. If testing is successful, will file necessary paperwork for recompletion.
- 8. If test fails complete the PxA. Squeeze Fruitland Sand perfs with 50 sx cement and isolate this and other water or gas-bearing zones per BLM requirements.
- 9. Cut off casing and wellhead. Install PxA marker according to BLM and/or state requirements.
- 10. Turn over to John Schwarz for reclamation.
- 11. Rehabilitate location according to BLM or state requirements.

If problems are encountered, please contact:

Irina Mitselmakher W: (303)830-4371 H: (303)369-9301