Form 9-331 (May 1963)

## UNITED STATES SUBMIT IN TRIPLICATE® DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved, Budget Bureau No. 42-R1424

5.	LEASE	DESIGNATION	AND	SERIAS.	NO.
	CD	077076		/	

GEOLOGICAL SURVEY					SF 077976/		
		AND REPORTS	ON WELLS thack to a different reservoir. proposals.)	6.	IF INDIAN, ALLOTTER	OR TRÉBE NAME	
1.				7.	UNIT AGREEMENT NA	MB	
WE'L GAS WELL	X OTHER			s	outheast Cha	Cha	
2. NAME OF OPERATOR				8.	PARM OR LEASE NAM	E	
Hicks Enco,							
3. ADDRESS OF OPERATOR					WELL NO.		
P. O. Box 174, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT		
See also space 17 bel At surface			Cha Cha Gallup				
	uth line and 7	'90' from East I	line	1	11. SEC., T., M., OR BLK. AND		
130 11011 30	ach tine and i	JO TTOM LABO	J.111C		SUBVEY OR AREA		
				S	ec. 17 - T28	N-R13W	
14. PERMIT NO.		ELEVATIONS (Show whether	DF, RT, GR, etc.)	1	2. COUNTY OR PARISH	13. STATE	
		6066 ground	i	S	an Juan	New Mexico	
16.	Check Appropr	riate Box To Indicate	Nature of Notice, Report,	, or Oth	er Data		
	NOTICE OF INTENTION TO				REPORT OF:		
	_ [ ]		WATER SHUT-OFF		REPAIRING W	FRUIT.	
TEST WATER SHUT-O		R ALTER CASING	FRACTURE TREATMENT		ALTERING CA	<del></del>	
SHOOT OR ACIDIZE	ABANDO	[]	SHOOTING OR ACIDIZIN	16 -	ABANDONMEN	ı	
REPAIR WELL	CHANGI	E PLANS	(Other)				
(Other) Aband	on Dakota	l l	(Nork: Report : Completion or R	results of ecompletic	multiple completion on Report and Log for	on Well m.)	
17. DESCRIBE PROPOSED O proposed work. I nent to this work.)	[ well is directionally of	es (Clearly state all perth drilled, give subsurface le	ent details, and give pertinent scations and measured and true	dates, inc vertical d	duding estimated date epths for all markers	e of starting any and zones perti-	
We want to a We will set a wireline d Mr. Al Greer	bandon the Dak a cast iron br ump bailer. R	tota formation a ridge plug @ 618 Run tubing and intin-Greer, the	kota and Gallup zon and produce the Gal B5' and dump 5 sks rods to produce Gal operator of the Da	<pre>lup fo of cem lup.</pre>	ent on top w	ith	
						300	

(This space for Federal or State office use)

al Frank

\*See Instructions on Reverse Side

JAMES F. SINS
DISTRICT OIL & GAS SUPERVISOR