

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATES
(Check instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078905

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals and do not send it back to a different reservoir.
(Use APPLICATION FOR PERMIT for such proposals.)

7. UNIT AGREEMENT NAME

Callegos Canyon Unit GPA "D"

8. FARM OR LEASE NAME

9. WELL NO.

259

10. FIELD AND POOL, OR WILDCAT

Pinon Gallup

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREASE/4 SE/4 Section 14,
T-28-N, R-12-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1. WELL ☐ GAS ☐ OIL ☐ OTHER ☒ **Water Injection**

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

740' FSL & 810' FWL

16. PERMIT NO.

17. ELEVATION (Show whether DF, RL, or, etc.)

5790' RDB

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NATURE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PLUG OR ALTER CASING ☐REPAIR FRACURE ☐MULTIPLE COMPLETION ☐SHOOTING OR ACIDIZING ☐ABANDON ☒REPAIR WELL ☐REPAIR FRACURE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐(Other) ☐(NOTE: Report results of multiple completion on Well
Completion Log or Recombination Report and Log form.)19. Describe the position or condition, or otherwise, of the state of pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.

The subject well is part of a water injection system that has been abandoned due to its uneconomical state. No casing is to be removed from the hole. It is desired to permanently plug and abandon this well in the following manner:

1. Spot 50 sacks cement over perforations at 5736-5728' and squeeze 20 sacks into formation.
2. Spot 15 sacks from 4470-4272' over bottom of Masaverde.
3. Spot 15 sacks from 3338-3140' over top of Masaverde.
4. Spot 10 sacks from 2692-2560' over Chacra.
5. Spot 20 sacks from 1864-1600' over Pictured Cliffs.
6. Spot 20 sacks from 264'-surface.
7. Cut off wellhead, erect PXA marker, and clean up location.

(Cement was circulated to surface when surface casing was run.)

REC-10-100

20. I hereby certify that the foregoing is true and correct.

SIGNED

Original Signed by

J. R. R. R.

Area Engineer

DATE

February 8, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.