ABANDON*
(other)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

		Bud	get Bureau No. 42–R1424	
	5.	LEASE		
1		SF 078863		
	6.	IF INDIAN, ALLOTTE	E OR TRIBE NAME	
_				
	7.	UNIT AGREEMENT	NAME	
ıt.				
	8.	FARM OR LEASE NA	ME	
		Krause WN Fe	deral	
	9.	WELL NO.		
		6E		
	10.	FIELD OR WILDCAT	NAME	
		Basin Dakota		
	11.	SEC., T., R., M., OR	BLK. AND SURVEY OR	
7		AREA		
	29-28N-11W			
	12.	COUNTY OR PARISI	13. STATE	
		San Juan	New Mexico	
	14.	API NO.		
	30-045-24125			

(Do not use this form for proposals to drill o'to deepen or plug back to a difference reservoir. Use Form 9–331–C for such proposals.) 1. oil gas well k x other well 2. NAME OF OPERATOR ARCO Oil and Gas Company Division of Atlantic Richfield Company 3. ADDRESS OF OPERATOR P. O. Box 5540, Denver, Colorado 80217 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AT SURFACE: 1520' FSL & 1520' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Approx the same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES

Mrs.

(NOTE: Report results of r whiple completion or zone

change on Form

15. ELEVATIONS (SHO'V DF, KDB, AND WD) 5772' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MI & RU Completion Unit. Spotted 100 gals 15% MSR @ 6250'. Perf'd

MI & RU Completion Unit. Spotted 100 gals 15% MSR @ 6250'. Perf'd Dakota @ 6218',20,22,24,26,28,30,32,35,37,40,42,47, - 13 holes. Trt'd with 1000 gals 15% MSR & 26 ball sealers. Spotted 100 gals 15% MSR @ 6176'. Perf'd Graneros @ 6132',34,36,47,49,51,61,63,66, - 9 holes. Trt'd with 1000 gals 2% KCL wtr & 26 ball sealers. Followed with 1000 gals MSR & 18 ball sealers. Frac'd Graneros-Dakota perfs 6132'-6247' with 69,000 gals 2% KCL wtr and 264,000# 20/40 mesh sand with 11,000 gals pad & 4,000 gals flush.

Subsurface Safety Valve: Manu. and Tybe _	Set @	Ft.			
18. I hereby certify that the foregoing is tru					
SIGNED W.A. Walther, Jr. TITLE Operations Managerbate 7-17-81)					
(This space for Federal or State office use)					
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	ز		

*See Instructions on Revice Side