

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
Meridian Oil Inc.

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
990' FSL, 1650' FWL Sec. 10 T-29-N, R-7-W, NMPM

5. Lease Number  
SF-078399  
6. If Indian, All. or  
Tribe Name  
7. Unit Agreement Name  
San Juan 29-7 Unit  
8. Well Name & Number  
San Juan 29-7 U #4  
9. API Well No.  
10. Field and Pool  
Blanco MV  
11. County and State  
Rio Arriba Co, NM

## 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

## Type of Submission

## Type of Action

☒ Notice of Intent☐ Abandonment☐ Change of Plans☐ Subsequent Report☐ Recompletion☐ New Construction☐ Final Abandonment☐ Plugging Back☐ Non-Routine Fracturing☐ Casing Repair☐ Water Shut off☐ Altering Casing☐ Conversion to Injection☒ Other - sidetrack workover

## 13. Describe Proposed or Completed Operations

It is intended to workover the subject well in the following manner:

TOOH w/tbg. If tbg is stuck, cut off tbg approx. 100' below csg shoe. Set a cmt ret near bottom of 7" csg. TIH w/2 3/8" tbg. CO, sting into ret. Test tbg to 2500 psi. Sting all the way through ret, load backside w/wtr, PT to 500 psi. Squeeze open hole w/cmt. Pull out of ret, spot cmt on top of ret. Pull up one joint and reverse excess cmt out. Run CBL. Perf squeeze holes above TOC and squeeze cmt to 50' above Ojo Alamo. Drl to 10' below 7" csg shoe and sidetrack using knuckle joint. Drill to 5800'. Run a full string of 4 1/2" csg and cmt. Selectively perf and frac the Mesa Verde formation. Return well to production.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (DW) Title Regulatory Affairs Date 12/18/92

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_

CONDITION OF APPROVAL, if any:

APPROVED

DEC 18 1992

AREA MANAGER