

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Phillips Petroleum Company

3. Address and Telephone No.

5525 Hwy. 64, NBU 3004,, Farmington, NM 87401 599-3454

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit H, 1520' FNL & 900' FEL
Section 9, T-29-N, R-5-W

5. Lease Designation and Serial No.

SF-080179

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

San Juan 29-5 Unit

8. Well Name and No.

S.J. 29-5 Unit #61

9. API Well No.

30-039-21028

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Pit Closure
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The pit associated with the subject well's separator has been closed.
Details of the closure are attached.

Ed Hasely
DEPUTY OIL & GAS INSPECTOR

OCT 31 1995

RECEIVED
MAY - 4 1995

OIL CON. DIV.
DBL 3

14. I hereby certify that the foregoing is true and correct

Signed Ed Hasely Title Environmental Engineer

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date 2/16/95

APPROVED

APR 27 1995

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NMOC

Date Remediation Started: N/A Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: N/A

Initial assessment showed soils to be clean at the surface and at
3' below pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 3' below pit bottom

Sample date 8/31/94 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 2

TPH 12

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST
OF MY KNOWLEDGE AND BELIEF.

DATE 2/16/95 PRINTED NAME Ed Hasely

SIGNATURE *Ed Hasely* and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT SUMMARY
 IN WELD DATE: SEPT 29, 1994
 C.M.C.

1994

ENVIROTECH, INC.

REVISION DATE: SEP 28, 1994													EPA METHOD 8030 PULSED AND 114AP												
CLOSURE													TOTAL												
PIT NO	WELL NAME	U.S. R.	PIT TYPE	RANK SCORE	STANDARD (PPM)	DATE	COMPLETION	SOIL TYPE	SAMPLE NO.	Organic Vapor Meter (PPM)	Recoverable (PPM)	Benzene	Toluene	Ethyl Benzene	Xylene	BTEX	STATUS								
PA220	SAN JUAN 29-7 #87	A112217	SEEP/CLAY	10	1000	07/13/94	NO	CLAY/SLT	11@ 3.0'	666	142							CLOSE							
									11@ 6.0'	664	246														
									11@ 8.0'	681	94														
									11@ 14.0'	677	242														
									11@ 7.0'	176	280														
PA226	SAN JUAN 30-5 #73 DK	B103005	SEEP	0	5000	08/17/94	NO	SHALE	11@ 12.0'	398								CLOSE							
									11@ 4.5'	1.5	36														
PA227	SAN JUAN 30-5 #61 MV	A153005	SEEP	10	1000	08/18/94	NO	CLAY	11@ 16.0'	490	66							CLOSE							
PA227A	SAN JUAN 29-8 #107	A362908	SEEP	10	1000	08/22/94	NO	CLAY	12@ 4.5'	48	166							CLOSE							
									12@ 7.0'	345	74														
278	SAN JUAN 29-8 #107	A362908	SEEP	10	100	08/07/93	NO	CLAY	11@ 5.5'	547	42715							REMEDIAL TO 5.5'							
									13@ 3.0'	5.9	ND							BEDROCK							
PA228	SAN JUAN 29-5 #81	B362903	SEEP			08/22/94	NO	SAND	11@ 5.5'	158	36							CLOSE							
									11@ 6.0'	157	36														
PA228	SAN JUAN 29-5 #80	N362905	SEEP	0	5000	08/22/94	NO	SANDY CLAY	11@ 5.5'	157	36							CLOSE							
									11@ 6.0'	6.5	34														
PA230	SAN JUAN 29-8 #86	M022906	SEEP	10	1000	08/23/94	NO	SLTY CLAY	11@ 4.0'	190	319							CLOSE							
PA231	SAN JUAN 29-8 #103 PC	K042905	SEEP	0	5000	08/23/94	NO	SLTY CLAY	11@ 4.5'	544	4720							CLOSE							
PA232	SAN JUAN 29-8 #114	A072908	SEEP	0	5000	08/23/94	NO	SLTY CLAY	11@ 7.0'	80	24							CLOSE							
PA233	SAN JUAN 29-5 #71	M162905	SEEP	10	1000	08/29/94	NO	CLAY/SHALE	11@ 5.5'	0	ND							CLOSE							
									11@ 6.0'	16	22														
PA234	SAN JUAN 30-5 #89	A333005	SEEP	0	5000	08/29/94	NO	CLAY/SHALE	11@ 4.5'	0	ND							CLOSE							
									11@ 7.0'	0	ND														
PA235	SAN JUAN 30-5 #100 DK	A343005	SEEP	0	5000	08/29/94	NO	SANDY SHALE	11@ 5.5'	0	ND							CLOSE							
PA236	SAN JUAN 29-5 #88	G212905	SEEP	10	1000	08/29/94	NO	SANDY CLAY	11@ 6.0'	288	359							CLOSE							
									11@ 11.0'	386	3380							REMEDIAL TO 6.0'							
37	SAN JUAN 29-5 #75	M222905	SEEP	10	1000	08/30/94	NO	SHDY CLAY	11@ 11.0'	425	290							CLOSE							
									11@ 6.0'	147	20														
PA238	SAN JUAN 29-5 #70	H122905	SEEP	10	1000	08/30/94	NO	CLAY	11@ 6.0'	466	7580							REMEDIAL TO 14.0'							
PA239	SAN JUAN 29-5 #67	C252905	SEEP	10	1000	08/30/94	NO	CLAY/SAND	11@ 11.0'	302	8980							BEDROCK							
									11@ 14.0'	218	1320														
PA240	SAN JUAN 29-5 #104 PC	B102905	SEEP	10	1000	08/31/94	NO	CLAY	11@ 0.5'	166	6740							REMEDIAL TO 4.0'							
									11@ 4.0'	140	36														
PA241	SAN JUAN 29-5 #61	H062905	SEEP	0	5000	08/31/94	NO	CLAY	11@ 4.5'	2	ND							CLOSE							
									11@ 7.0'	2	12														
PA242	SAN JUAN 29-5 #59	H112905	SEEP	10	1000	08/31/94	NO	CLAY/SAND	11@ 7.0'	470	5840							REMEDIAL TO 11.0'							
									11@ 11.0'	84	32							BEDROCK							
PA243	SAN JUAN 29-8 #78	L222906	SEEP	0	5000	08/31/94	NO	CLAY	11@ 4.5'	0	16							CLOSE							
									11@ 7.0'	0	14														

ENVIROTECH INC.

1790 US HWY 64 FARMINGTON NM 87401
505-622-0615

PA247

FIELD REPORT SITE ASSESSMENT

93162
1 1 1

PHILLIPS Petroleum
ENVIROTECH INC.

8/31/94
CWC

LEASE SF 080179 WELL San Juan 295 02 Unit N° 61
SEC 9 TWP 29N R10E NW NM NMPT Sep
Range


57 feet NW
0'-3' clay tan, Brn, soft, dry, no odor

T1@7'	204	10	20	2	6	12.0
T1@4.5	705	10	20	2	3	6.0

140'
not
71000'
0
25000

SAMPLE INVENTORY		
SMPL ID	SMPL TYPE	LABORATORY ANALYSIS

SCALE
0 20 FEET
SITE DIAGRAM




separator

TH=	TH=	TH=	TH=
SOIL TYPE	SMPL TYPE	SMPL TYPE	SMPL OVN TYPE
0			
1			
2			
3			
4			
5			
6			
7			

2.0/8 TM/
Clay Brn. 6.0
Clay Brn, soft. 2.0/2.0

Grading F - Poorly, W - Well



ENVIROTECH LABS

5796 US HIGHWAY 64-3014 • FARMINGTON, NEW MEXICO 87401
PHONE: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client: Phillips Petroleum
Sample ID: T-1 @ 7.0'
Project Location: San Juan 29-5 #61
Laboratory Number: GAC0704

Project #: 93163
Date Analyzed: 8-31-94
Date Reported: 9-23-94
Sample Matrix: Soil

Parameter	Result, mg/kg	Detection Limit, mg/kg
Total Recoverable Petroleum Hydrocarbons	12	10

ND = Not Detectable at stated detection limits.

QA/QC:	QA/QC Sample TPH mg/kg	Duplicate TPH mg/kg	% *Diff.
	2	2	0


*Administrative Acceptance limits set at 30%.

Method: Modified Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and Waste, USEPA Storet No.4551, 1978

Comments: Separator Pit PA241

Analyst

Review



ENVIROTECH LABS

5796 US HIGHWAY 64-3014 • FARMINGTON, NEW MEXICO 87401
PHONE: (505) 632-0615 • FAX: (505) 632-1865

FIELD MODIFIED EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	Phillips Petroleum	Project #:	93163
Sample ID:	T-1 @ 4.5'	Date Analyzed:	8-31-94
Project Location:	San Juan 29-5 #61	Date Reported:	9-23-94
Laboratory Number:	GAC0705	Sample Matrix:	Soil

Parameter	Result, mg/kg	Detection Limit, mg/kg
Total Recoverable Petroleum Hydrocarbons	6	10

ND = Not Detectable at stated detection limits.


QA/QC:	QA/QC Sample TPH mg/kg	Duplicate TPH mg/kg	% *Diff.
	2	2	0

*Administrative Acceptance limits set at 30%.

Method: Modified Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and Waste, USEPA Storet No.4551, 1978

Comments: Separator Pit PA241


Analyst


Review