Form	3160-5
(June	1990)

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

Buaget Bur	eau No.	1004-0135
Expires:	March 3	1, 1993

5. Lease Designation and Serial No.

SF-078282 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well San Juan 29-5 Unit 8. Well Name and No. 2. Name of Operator -SJ 29-5 Unit #27A Phillips Petroleum Company 9. API Well No. 3. Address and Telephone No. 30-039-21558 5525 Highway 64, NBU 3004, Farmington, NM 87401 10. Field and Pool, or exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit I, 1600' FSL & 790' FEL Blanco Mesaverde Section 19, T29N, R5W 11. County or Parish, State Rio Arriba. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Back

Casing Repair

Altering Casing

Attached is the procedure used to perforate and stimulate the Lewis Shale interval of the Mesaverde formation on the subject well.



Add pay & Stimulate



Non-Routine Fracturing

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Water Shut-Off

Dispose Water

		*	
14. I hereby certify that the toragoing is true and correct Signed Alse Mess Tor	Title	Regulatory Assistant	HECEDTED FAR REPORTS
(This space for Federal or State office use)	Title		ACCEPTED FUNKECOND
Approved by	Title		1006 0.000
Conditions of approval, if any:			JAN 0 9 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State Of t or representations as to any matter within its jurisdiction

San Juan 29-5 Unit #27A SF-078282; Unit I, 1600' FSL & 790' FEL Sec. 19, T29N, R6W; Rio Arriba County, New Mexico

Details of the procedure used to perf the Lewis Shale intervals of the Mesaverde formation and stimulate.

12/17/97

MIRU Big A #29. Kill well with water. ND WH & install BPV. NU BOPs. PT -200 psi for 10 min. 3000 psi for 20 min. - OK. RIH w/bit & scraper to 5900'. COOH. RU Blue Jet & set 4 ½" RBP on WL @ 5200'. Dump bail 10 gal sand on top of RBP. Run cased hole GR, CCL log. PT RBP, casing, blinds to 500 psi 30 min. Held OK. RU to perf the Lewis Shale w/40 (.38") holes @ 1spf. As follows:

4901' - 4906' (5');	4788' - 4793' (5');	4720' - 4725' (5');
4647' - 4652' (5');	4572' - 4577' (5');	4484' - 4489' (5');
4448' - 4453' (5');	4430' - 4435' (5');	Total 40 holes

RIH w/4 ½" RBP & set @ 4194'. RU BJ to acidize. Pumped 1000 gal 15% HCL & ballsealers. RIH & retrieved most of the balls. RU to frac. PT lines - OK. Pumped 72,030 gal of 60 Quality N2 fooam consisting of 33,600 gal of 30# linear gel & 844 mscf of N2 gas. Pumped 209,328# of 20/40 Arizona sand @ 40 bpm (avg.) and avg. TP - 2810'. ISDP - 4950 psi. Flowed back immediately on ¼" choke for 33 hrs.

RD frac head. COOH w/packer. Cleaned out fill with air. POOH w/RBP. RIH & Land tubing 5948' with "F" nipple on top of bottom joint. ND BOPs. NU WH. Pull BPV. PT tubing to 1000 psi. Pump off check. RD & released rig 12/23/97. Turned well over to production department.