Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No. NM-012698 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well San Juan 29-6 Unit Oil χ Gas 8. Well Name and No. 2. Name of Operator SJ 29-6 Unit #21A Phillips Petroleum Company 9. API Well No. 3. Address and Telephone No. 30-039-21567 5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454 10. Field and Pool, or exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit P, 880' FSL & 950' FEL Blanco Mesaverde Section 11. T29N. R6W 11. County or Parish, State Rio Arriba. NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Add pay & stimulate Other ____ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* See the attached for details on the procedure used to add Lewis Shale pay to the existing Mesaverde formation and stimulate. OIL CON. DIV Regulatory Assistant (This space for Federal or State office use) Approved by Conditions of approval, if any: DEC 1 6 1997 Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudule or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

San Juan 29-6 Unit #21A Unit P, 880' FSL & 950' FEL Section 11, T29N, R6W

Details of procedure used to add Lewis Shale pay to existing MV & stimulate.

11/26/97

MIRU Big A #40. Kill well w/2% KCl. ND WH & installed BPV. NU BOPs. PT - OK. Pulled BPV. COOH w/tubing. RIH w/bit & scraper. COOH. RU Blue Jet & set RBP (4 ½") at 5000'. Dumped 10 gal sand on top of RBP. Ran GR/CCL log from 4980' - 3750'. Perfd Lewis Shale formation w/40 (.38" holes) as follows:

```
4844' - 4849' (5'); 4770' - 4775' (5'); 4714' - 4719' (5'); 4630' - 4635' (5'); 4570' - 4575' (5'); 4487' - 4492' (5'); 4468' - 4473' (5'); 4446' - 4451' (5') Total 40 holes.
```

RIH w/4 ½" packer and set @ 4223'. PT annulus to 500 psi - OK. RU BJ to acidize. Pumped 1500 gal of 15% HCL & ballsealers. Released packer & retrieved balls. Reset packer @ 3838'. PT - OK. RU to frac. Pumped 74,156 gal of 60 Quality N_2 foam consisting of 32,760 gal of 30# Linear gel & 900,000 scf N_2 . Pumped a total of 201,960 # 20/40 Arizona sand. Avg. rate 40 bpm and avg. treating pressure 3300 psi. ISDP 850 psi. Flowed back immediately on ¼" choke for 41 ½ hrs.

RD Frac Head. Clean out fill w/air. COOH w/RBP. RIH w/2-3/8" tubing. Circ. Hole clean. Landed tubing @ 5995'. ND BOPs and NU WH. Pull BPV. PT - 1000 psi - OK. Pump off check. RD & MO. Turned well over to production department.