



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

July 20, 1994

MR ED HASELY
PHILLIPS PETROLEUM CO
5525 HWY 64 NBU 3004
FARMINGTON NM 87401

RE: SAN JUAN 29-5 UNIT #100 G-25-29N-05W

Dear Ed:

The 1994 Packer Leakage Test on the referenced well was inconclusive. Reschedule and retest the well in such a manner as to prove zone separation. Shut both zones in for a minimum of 3 days. Flow the higher pressured zone to the atmosphere until the pressure decreases enough to determine if there is zone separation. Notify this office at least 24 hours prior to the test so we may provide a witness. The test must be conducted prior to January 1, 1995.

Yours Truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/cs

· xc: Well files