Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTEDIOR

FO	RM	ΑP	P	RO'	V	E	D	

Budget Bureau No. 1004-0135

ARIMENI OF THE INTERIOR	Expires: March 31,
EAU OF LAND MANAGEMENT	5. Lease Designation and Ser

BUREAU OF I	LAND MANAGEMENT	5. Lease Designation and Serial No.		
SUNDRY NOTICES AND Do not use this form for proposals to drill	SF-078410 6. If Indian, Allottee or Tribe Name			
Use "APPLICATION FOR	PERMIT - " for such proposals			
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well		San Juan 29-5 Unit		
Oil X Gas Other		8. Well Name and No.		
2. Name of Operator		SJ 29-5 Unit #203		
Phillips Petroleum Company		9. API Well No.		
3. Address and Telephone No.		30-039-24535		
5525 Highway 64, NBU 3004, Farming	10. Field and Pool, or exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey De				
Unit B. 955' FNL & 1850' FEL		Basin Fruitland Coal		
Section 6. T29N, R5W		11. County or Parish, State		
Section 6, 125N, NSW		Rio Arriba, NM		
12. CHECK APPROPRIATE BOX(S	)-TO INDICATE NATURE OF NOTICE, REPORT	T, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	N		
X Notice of Inten C C C C	Abandonment	Change of Plans		
Notice of InterDECE	WE Recompletion	New Construction		
Subsequent Rendal		No. Bouting Fracturing		
MAR - 9	Plugging Back	Non-Routine Fracturing		
	1998 Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing	Conversion to Injection		
OUL GOING	Recavitate well	Dispose Water		
DIGT.	g	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
Describe Proposed or Completed Operations (Clearly state a)	l pertinent details, and give pertinent dates, including estimated date of sta			
give subsurface locations and measured and true ver	tical depths for all markers and zones pertinent to this work.)*			

A  $5 \cdot 1/2$ " uncemented liner was run during compeltion operations. Plans are to pull the tubing and liner. cleanout to TD, recavitate the coal interval, possibly run a new 5-1/2" liner, perforate, land tubing and return to production. A brief description of the work planned is as follows:

MIRU. Install BPV and ND tree. NU & test BOP. Retrieve BPV. POOH w/tubing. Pull 5-1/2" liner. RIH w/b t on 2-7/8" DP & cleanout to TD. PU and recavitate coal interval. POOH. It hasn't been decided if a liner will be run back in hole, but if it is, they will run a new 5-1/2" 15.5# J-55 liner with hanger and packer. Set liner on bottom. Set hanger and packer. If required RU wireline and perforate liner. RIH with tubing and land. Set BPV. ND BOP & NU & test tree. Retrieve BPV and return well to production.

A 25' X 60' lined (3 sided fenced) pit will be utilized during workover.

				. 1.5
14. Thereby certify that the foregoing is rue and correct  Signed  Output  Disput  Signed	Title	Regulatory Assistant	Date -	3-3-98
(This space for Federal or State office use)  Approved by	Title		Date -	MAR - 6 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction