FORM APPROVED **UNITED STATES** DEPARTMENT OF THE INTERIOR Budget Bureau No. 1004-0135 Form 3160-5 BUREAU OF LAND MANAGEMENT Expires March 31, 1993 (June 1990) 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NMNM-18327 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT -" for such proposals 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well Other Gas Well Oil Well 8. Weil Name and No. 2. Name of Operator 29-4 Carson 28 # 1 Synergy Operating, LLC 9. API Well No. 3. Address and Telephone No. 30-039-2467300 (505) 325-5449 PO Box 5513 10. Field and Pool, or Expioratory Farmington, NM 87499 4. Location of Well (Footage, Sec, T. R., M, or Survey Description) Wildcat NACIMIENTO 11. County or Parish, State 1905' FSL & 1604' FWL Sec 28, T29N, ROWY Rio Arriba County New Mexico 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandoment Notice of Intent **New Construction** Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Altering Casing Converion to Injection Final Abandonment Notice Dispose Water Other Completion or recompletion Report and Log Form) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work. If well is directionally drifted give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work. Synergy Operating, LLC completed the following work to Temporarily Abandon the subject well. 06-24-2002 MIRU Key Rig # 38. Fire Watch H2O truck on location. COOH, LD 81- 7/8" rods & pump. ND WH, NU BOPE COOH w/ 69 jts 2-7/8", LD BHA. GIH w/ 5-1/2" CIBP on tubing, set CIBP @ 1827', above San Jose perforations Top perf @ 1906'. Load hole w/ 29 bbls. Test Casing & CIBP to 500 psi. Good test. COOH w/ setting tool. LD setting tool. GIH and land 59 jts of 2-7/8" tubing @ 1797'. Install hanger. ND BOPE, NU WH. Install Polish Rod, RDMO Key Rig # 38 to Sunray B # 4. Well is in an official temporary abandoned status. This wellbore may have use to be re-entered and restored to production in the Fruittand Coal, or converted to a water supply well. 14. I hereby certify that the oregoing is true and 07-05-2002 Date: Engineering Manager Signed: Thomas E. Mullins This space for federal or state office use Date Approved by: Conditions of approval if any Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent

COOME

or representations as to any matter within its jurisdiction

FARMING ON THE OFFICE