

United States Department of the Interior

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LAPLATA HIGHWAY FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

SF-078282 et al. (WC) 3162.3-1(F) (019)

JUN. 20 1991

RECEIVED

OIL CON. DIV.

JUN 2

Gentlemen:

Phillips Petroleum Company

5525 Highway 64, NBU 3004 Farmington, NM 87401

Enclosed are your Applications for Permit to Drill (APDs) well Nos.:

- 1. No. 204 San Juan 29-5 Unit, NW/4NE/4, sec. 19, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
- 2. No. 205 San Juan 29-5 Unit, NW/4NE/4, sec. 20, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078281.
- 3. No. 208 San Juan 29-5 Unit, SW/4SW/4, sec. 21, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, NM-03188.
- 4. No. 209 San Juan 29-5 Unit, SE/4NE/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
- 5. No. 210 San Juan 29-5 Unit, SE/4SW/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
- 6. No. 211 San Juan 29-5 Unit, SE/4NE/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
- 7. No. 212 San Juan 29-5 Unit, SE/4SW/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
- 8. No. 205/San Juan 32-7 Unit, SE/4SW/4, sec. 22, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078459.
- 9. No. 206 $\sqrt{\text{San}}$ Juan 32-7 Unit, SW/4NE/4, sec. 27, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078472.

As discussed with Gail Bearden of your company on June 10, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no

ABANDONED LOCATION

construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Isl Duane Spencer

John L. Keller
Chief, Branch of Mineral Resources

9 Enclosures

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410