Form 3160-5 (June 1490)

UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

FORM	I APPRO	VED	/
Budget Bur	eau No.	10044	1135
Expires:	March 3	199	93

BUREAU OF LAND MANAGEMENT

ECEIVED SF-07

S	UNDRY I	NOTICES	AND	REPORTS	ON	WELLS	KEGEIV	E
Do not use this form	for propo	osals to di	rill or	to deepen	or re	entry to a d	ifferent res ervoir	•
Use	"APPLIC	ATION FO	R PE	RMIT - " fo	r suc	h proposals	Q5 ## 21 a	

SUBMIT IN TRIPLICATE

6. If Indian, Allottee or Tribe Name

Z. Unit or CA, Agreement Designation

5. Lease Designation and Serial No.

		OTA PARLEY	9-1 00 6 11 11
1. Type of Well Oil Y Gas		070 FARMINGTON, A	an Juan 29-6 Unit
Oil X Gas Well Other 2. Name of Operator			,
Phillips Petroleum Company		<u> </u>	SJ: 29-6 #225 9. API Well No.
3. Address and Telephone No.			30-039-24682
5525 Highway 64, NBU 3004, Fa		505-599-3454	10. Field and Pool, or exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey De Unit L, 1390' FSL & 1305' FW			Pacin Enuitland Coal
Section 13, T-29-N, R-6-W	L	<u> </u>	Basin Fruitland Coal 11. County or Parish, State
56661611 26, 1 25 II, K 6 II			Rio Arriba NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE	OF NOTICE, REPORT, O	R OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
X Notice of Intent	X Abandonmen	t	Change of Plans
	Recompletion	1	New Construction
Subsequent Report	Plugging Bac	k	Non-Routine Fracturing
Final Abandonment Notice	ලිලිලි 🖅 🖳 Casing Repai	r	Water Shut-Off
	Altering Casi	ng	Conversion to Injection
	DIVO U Other		Dispose Water (Note: Report results of multiple completion on Well
13. Describe Proposed or Completed Operations (Clearly state all	pertinent details, and give pertinent dates	s, including estimated date of starting	Completion or Recompletion Report and Log form.) any proposed work. If well is directionally drille
The cement to be used in this P excess outside pipe and 50' insviscosity. POOH 2-3/8" tubing. Set CIBP @ to isolate Fruitland Coal. POO well for a minimum of 30 minute face. POOH to 3022'. Spot bal Ojo Alamo. POOH above cement t isolate Nacimento. POOH above surface. ND BOP, cut off wellh restore location to BLM's speci 1995.	aide; corrosion inhib a 3330'. GIH with 2- bH above cement, circ es to ensure integrit anced plug (51 sxs) to 1675'. Spot balan cement to 368'. Cir mead below surface ca	aited fluid will be 3/8" tubing, dump culate corrosion in dy of CIBP & fluid from 3022' to 2752 deed plug (28 sxs) culate cement (69 desing flange, insta	8.4 ppg with a 40 sec. cement (33 sxs) on top hibited fluid. Monitor level is stable at sur- ' to isolate Kirtland/ from 1675' to 1525' to sxs) from 368' to ll P&A marker and
14. I hereby certify that the foregoing is true and correct Signed (This space for Federal or State office use) Approved by Conditions of approval, if any:	Title Envir./Reg	ulatory Engineer	

* See Instruction on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State or representations as to any matter within its jurisdiction.