

F

30-039-24695

04-16-90

F. Loc. 1455/N; 825/E Elev. 6752 GL Spd. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W' _____ Sx. Int. _____ @ _____ W _____ Cu. ft. _____
 Csg. Perf. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NITD		X		Well Log		TEST DATA							
Ojo Alamo		C - 103				Plat		X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C - 104				Electric Log									
Fruitland						C - 122									
Pictured Cliffs		Ditr				Dfa									
Chacra		Datr				Dac									
Cliff House															
Menefee															
Point Lookout															
Mancos															
Gallup															
Greenhorn															
Dakota															
Entrada															
						Acres		E/320							

P
o
o
i

BasinFrCoal Co. RA S 30 T 29N R 05W UH Oper. Phillips Petroleum Lse. San Juan 29-5 Unit No. 211

San Juan 29-5 Unit #211

H-30-29N-05W

PHILLIPS PETROLEUM CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

SF-078282 et al. (WC)
3162.3-1(F) (019)

JUN. 20 1991

RECEIVED
JUN 21 1991.
OIL CON. DIV.
DIST. 3

Phillips Petroleum Company
5525 Highway 64, NBU 3004
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) well Nos.:

1. No. 204 ✓ San Juan 29-5 Unit, NW/4NE/4, sec. 19, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
2. No. 205 ✓ San Juan 29-5 Unit, NW/4NE/4, sec. 20, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078281.
3. No. 208 ✓ San Juan 29-5 Unit, SW/4SW/4, sec. 21, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, NM-03188.
4. No. 209 ✓ San Juan 29-5 Unit, SE/4NE/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
5. No. 210 ✓ San Juan 29-5 Unit, SE/4SW/4, sec. 29, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-078282.
6. No. 211 ✓ San Juan 29-5 Unit, SE/4NE/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
7. No. 212 ✓ San Juan 29-5 Unit, SE/4SW/4, sec. 30, T. 29 N., R. 5 W., Rio Arriba County, New Mexico, SF-079851.
8. No. 205 ✓ San Juan 32-7 Unit, SE/4SW/4, sec. 22, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078459.
9. No. 206 ✓ San Juan 32-7 Unit, SW/4NE/4, sec. 27, T. 32 N., R. 7 W., San Juan County, New Mexico, SF-078472.

As discussed with Gail Bearden of your company on June 10, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no

ABANDONED LOCATION

construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ Duane Spencer

FOR John L. Keller
Chief, Branch of Mineral Resources

9 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410