BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals SUBMIT IN TRIPLICATE 1. Type of Well	No. ame esignation t
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	t y Area
SUBMIT IN TRIPLICATE 7. If Unit or CA. Agreement D San Juan 29-6 Unit San Juan 29-6 Unit 8. Well Name and No. 8. Well Name and No. 8. Well Name and No. 9. API Well No. 9. API	y Area
Oil Walt Other State Other	y Area
2. Name of Operator Phillips Petroleum Company 3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit A, 803 * FNL 7 1152 * FEL Section 19, T29N, R6W 11. County or Parish, State Rio Arriba, 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans	oal
3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454 4. Location of Well (Feotage, Sec., T., R., M., or Survey Description) Unit A, 803' FNL 7 1152' FEL Section 19, T29N, R6W Basin Fruitland C II. County or Parish, State Rio Arriba. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Recompletion Recompletion Plugging Back Casing Repair Ald6 2 5 1837 Plugging Back Conversion to Injection Dispose Water (Noor. Report reads of mathies recompletion beyon conversation and measured and true vertical depths for all markers and zones pertinent to this work.)* Plans are to try & control where the gas and water seperation occurs. This should sol several production problems. Details of the procedure are as follows: 1. Set Wireline plugs. 2. ND WH & NU BOPS. 3. POOH w/tubing. 4. Glih w/tubing, packer and on/off tool. Set EOT @ bottom perf & packer @ TOL. Relefrom on/off tool, PU 5' and land tubing. 5. ND BOPs and NU WH. 6. Return well to production.	oal
Hostion of Well (Footage, Sec., T., R., M., or Survey Description) Unit A, 803' FNL 7 1152' FEL Section 19, T29N, R6W Rio Arriba, State Rio Arriba,	oal
TYPE OF SUBMISSION Notice of Intent	
Abandonment Subsequent Report AU6 2 5 1807 Recompletion New Construction Non-Routine Fracturing Water Shut-Off Cosing Repair Conversion to Injection Dispose Water Conversion or Recompletion Conversion to Injection Dispose Water Conversion or Recompletion or Re	
Recompletion New Construction Non-Routine Fracturing Water Shut-Off	
Plans are to try & control where the gas and water seperation occurs. This should sol several production problems. Details of the procedure are as follows: 1. Set Wireline plugs. 2. ND WH & NU BOPs. 3. POOH w/tubing. 4. GIH w/tubing, packer and on/off tool. Set EOT @ bottom perf & packer @ TOL. Relefrom on/off tool, PU 5' and land tubing. 5. ND BOPs and NU WH. 6. Return well to production.	ind Log form.)
 Set Wireline plugs. ND WH & NU BOPs. POOH w/tubing. GIH w/tubing, packer and on/off tool. Set EOT @ bottom perf & packer @ TOL. Rele from on/off tool, PU 5' and land tubing. ND BOPs and NU WH. Return well to production. 	tionally drilled
 ND WH & NU BOPs. POOH w/tubing. GIH w/tubing, packer and on/off tool. Set EOT @ bottom perf & packer @ TOL. Rele from on/off tool, PU 5' and land tubing. ND BOPs and NU WH. Return well to production. 	ve
A FION DUCK CUIK WITH DC UCTITZCU HISCEUU OL B WOLKOVEL DIL.	ase
20 KH 9: 39	(1) (C) (C) (T)
14. I hereby certify that the foregoing is true and correct Signed Atsac Cuss Title Regulatory Assistant Date 8-20-9	
(This space for Federal of State office use) AUG 22 193	= 7
Approved by Spencer Title Date	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudule	

Form 3160-5

or representations as to any matter within its jurisdiction.