

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE/DESIGNATION AND SERIAL NO. 14-20-603-1043	
2. NAME OF OPERATOR SUN OIL COMPANY - DX DIVISION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo	
3. ADDRESS OF OPERATOR P. O. Box 1416 Roswell, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790' FSL, 1980' FEL, Sec 27, T-28-N, R-17-W		8. FARM OR LEASE NAME Navajo Table Mesa	
14. PERMIT NO.		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5363KB		10. FIELD AND POOL, OR WILDCAT Undesignated Paradox	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 27, T-28-N, R-17-W	
		12. COUNTY OR PARISH San Juan	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- (1). Pulled tubing and hydraulic pump.
- (2). Laid 50 sx plug from 7302' to 6652' w/tubing. WOC. 12 hrs.
- (3). Had full 2" water stream from SWD zone between 5 1/2"-9 5/8" csg. Perf 5 1/2" csg from 5525'-23' w/8 holes. Pumped 50 sx ent down 5 1/2" csg to 1500 psi. WOC overnight. Had small water flow from 5 1/2" to 9 5/8" csg annulus.
- (4). Cut 5 1/2" csg @ 5255', and POOH.
- (5). Ran tubing, tagged plug at 5264'. Picked up to 5259', spotted 75 sx plug class A neat. Pulled tubing. Had back flow (3 gal/hr). Squeezed w/25 sx to 1035 psi., w/tubing @ 4776', WOC 18 hrs. TOC 4712'. Pressured up to 935 psi. Plug held ok.
- (6). Set 35 sx plug from 85' to surface.
- (7). Installed dry hole marker 8-6-69. Clearing location. Will notify when ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED F. D. Lebo TITLE District Engineer DATE 8-19-69

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

AUG 21 1969

U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.