5.

0

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office Senta Fe V
Lease No. SF 078125
Unit E/2, Sec. 34, T-29N, R-7W,
N.M.P.M. Rio Arriba County

New Mexico.

Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUEN	T REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-		REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAI	R WELL SUBSEQUENT	T REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT	T REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CAS	SING SUPPLEMENT	TARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
(INDICATE ABOVE	BY CHECK MARK NATURE OF REPOR	IT, NOTICE, OR OTHER DATA)	
	•••••	June 5	, 19 5 8
San Juan Unit 29 Well No. 60/ is located 10 WE/1, WE/1, Section 34	-	· · ·	<u> </u>
0, 200, 200, 200, 200, 200, 200, 200, 2			
blanco Mesaverde	(County of Subdivision)	(State or Thinkery)	∖ ك.، تست
	1 1 21 44	437	1 6 1958
The elevation of the derrick floor a	bove sea level is bust	. 11.	-
	DETAILS OF WOR	RK	The COM.
(State names of and expected depths to objective		. الساد الماد ا	jobs, coment
(State names of and expected depths to objective ing	points, and all other important pr	oposed work)	-
n 65 joints (2418 ft.) of $5\frac{1}{5}$ ner at 3181, bottom at 5599	, J-55, 15.5# csg. (R.K.B. cemented with	as a liner on May 25, 1956 h 275 sacks regular cement	8, top of t with 4% g
eaned out hole to 5559 on May	26, 1958, pressure	d up on liner to 1000 psi	, pressure
orf. 5399-5497 2 shots/ft. sand sand, set magnesium bridge por ft. Sand water frac. with 8	olug at 5152. Perf.	5052-4936, 4900-4890, 48°	70-4040 Z I
illing bridge plug and cleane	d out to 5559.		
n 175 joints ?", 4.70#, J-55	tbg.landed at 5551	on May 28, 1958.	
I understand that this plan of work must re-	ceive approval in writing by the Ge	ological Survey before operations may be com	nmenced.
Company SOUTHERN UNION C	ias comapeny		
Address 1001 Burt Buildi	ing		111
Dallas, Texas	_	By Mul L. O.	late)
	Т	Title Drilling Superintend	ent