UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

•		
?	RECEL	, Ci

	BONEAU	OF INIO MANAGEMENT	REUELL E			
	Sundry Not:	ices and Reports or	wells	5		
1. Ty	ype of Well GAS	93 0 7	AUS 27 PH 2: L O FARMINGTON, I	5. VM ₆ .	Lease Number SF-078945 If Indian, All. or Tribe Name	
2. Na	ame of Operator	1.56	<u> </u>	7.	Unit Agreement Name	
1	RESOURCES OIL	& GAS COMPANY "U	SEP 1 4 1000] }}.	San Juan 29-7 Unit Well Name & Number San Juan 29-7 U #42	
	ddress & Phone No. of Operation of Well, Footage, Sec. 29, 1	50., 1, 10, M		•	API Well No. 30-039-07540 Field and Pool Blanco Mesaverde County and State Rio Arriba Co, NM	
	CHECK APPROPRIATE BOX TO INI			OTHER	DATA	
13	<pre>pe of Submission</pre>	Abandonment Recompletion Plugging Back Casing Repair	: Non-Rou	struct tine I hut of	cion Fracturing Ef	
		X Other - Tubir		1011 60	o injection	
13.	Describe Proposed or Compl	leted Operations		. <u></u> .		
	Attempt to dres 8-4-98 TIH w/inflatable p	to pass through to s top of csg. SDON kr, set @ 1100'. To OK. NU BOP. Relea. 8" 4.7# J-55 EUE to	p of 4 ½" csg. DOH. ND BOP. C se pkr, TOOH. :	TOOH. nange SDON.	TIH w/tapered mill.	
		nig rorododu.				
14.	I hereby certify that the	foregoing is true		r Data	. 8/25/00	
_no	space for Federal or State					
APPRO	OVED BY TION OF APPROVAL, if any:	Title	Da	t AUÜ E	PTED FOR RECORD	
					SEP 0 8 1998	

THIMINGTON DISTRICT OFFICE