## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sund	dry Notices and Reports on Wells	· [[] [] 3 [		
l. <b>Type of Well</b> GAS		cH, NM	5. 6.	Lease Number SF-078919 If Indian, All. or Tribe Name
	DEC 1 5 1994		7.	Unit Agreement Name
MERIDIAN OIL	@[il @@[n]. D[]V. 		8.	San Juan 29-7 Unit Well Name & Number San Juan 29-7 U #37
3. Address & Phone No. of PO Box 4289, Farming	f Operator ton, NM 87499 (505) 326-9700		9.	
4. Location of Well, Foo	tage, Sec., T, R, M ec.12, T-29-N, R-7-W, NMPM		10.	Field and Pool Blanco Mesaverde
1001 FSL, 1650 FWL, 5	ec.12, 1-29-N, K / W, MMIN		11.	County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BO	X TO INDICATE NATURE OF NOTICE,	REPORT, C	THER	DATA
It is intended to that there shot and so will then a cement and run in the top of ceme cement will be pressure patched bac will be se	_X_ Casing Repair	determine ay intervito cover casing willed out 5 1/2" ca hole will cement to be run. w bond log 321' and yely perfo	e the al, sthe il be of the surf. The stimurated	top of cement. Given squeeze holes will be interval. The squeeze cut above the top of he hole. A CBL will be to surface. Once the shot and sufficient face. The 7" casing will be the Menefee intervalulated with 110,000 from 3933-4818' and
I hereby certify to Signed Man Man (This space for Federal	chat the foregoing is true and control (JCG7) Title Regulator or State Office use) Title			te 12/6/94
APPROVED BY CONDITION OF APPROVAL, i			- <del>-</del> _	APPROVEU

DEC Nº 1994 NOTRICT MONAGED