
Form 9-881 a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office. Senta Fe

Lease No. SF 078423

Umit E/2 Sec.11, T-29N, Re7W
N.M.P.M., Rio Arriba

County, New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

HOUSE OF INTERTION TO DRIBE	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	
<u></u>	1
(INDICATE ABOVE BY CHECK MARK NATU	RE OF REPORT, NOTICE, OR OTHER DATA)
San Juan Unit 29-7  Well No. 64 is located 1840 ft. from     No. 64   Section 11   T-29N   R-7  (34 Sec. and Sec. No.) (Twp.) (Range	
Blacno Mesa Verde Rio Arriba Count	New Mexico M4727
(Field) (County or Subd	livision) (State or Territor)) 1958
SE/1. NE/1. Section 11 T-29N R-7W N. M. P.M.  (b) Section 11 T-29N R-7W (Meridian)  (County or Subdivision)  (County or Subdivision)  (State or Territor)  (CON CON COM  (CON CON  (CON CON  (CON  (CO	
DETAILS OF WORK  State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)	
- Cleaned out hole to 5576 on May 6, 1 pressure held.	958 - pressured up esg. to 1800 psi -
S - Perf. 5380-5480 Sand water frac. w/l Set Magnesium Bridge plug at 5300 - 5056-4960 sand water frac. w/75,000	Perf. 5276-5246, 5224-5210, 5175-5160,
- Drilled Bridge plug and cleaned out - Ran 177 joints 2" tbg. landed at 518 I understand that this plan of work must receive approval in writing	O R.K.B.
Company SOUTHERN UNION GAS COMPANY	
Address 1001 Burt Building	277111
Dallas, Texas	By Mine Late
	Title Drilling Superintendent
	GPO 918507