

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM MAIL ROOM

Sundry Notices and Reports on 95 OCT 10 PM 2:56

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
2020' FSL, 1470' FWL, Sec. 33, T-29-N, R-7-W, NMPM

070 FARMINGTON, NM

Lease Number
SF-078503

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

San Juan 29-7 Unit

8. Well Name & Number
San Juan 29-7 U #114

9. API Well No.
30-039-21747

10. Field and Pool
Basin Dakota

11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☒ Other - Tubing repair	

13. Describe Proposed or Completed Operations

10-2-95 MIRU. ND WH. NU BOP. TIH, tag fill @ 7782'. TOOH w/241 jts 1 1/2" tbhg. TIH w/4 1/2" csg scraper. SDON.

10-3-95 TIH w/csg scraper to 7512'. Load tbhg w/wtr. PT tbhg, found 2 holes in tbhg. TOOH w/csg scraper. TIH w/Model D pkr, set @ 7511'. Pump 120 bbl 2% Kcl wtr on backside to PT csg, failed. SDON.

10-4-95 Load hole w/145 bbl wtr. PT csg, failed. TIH w/241 jts 1 1/2" 2.33# J-55 tbhg, landed @ 7777'. Reset Model "D" pkr @ 7523' to isolate csg failure. TOOH. ND BOP. NU WH. RD. Rig released.

RECEIVED
OCT 16 1995

OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed: [Signature] Title Regulatory Administrator Date 10/9/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

ACCEPTED FOR RECORD

OCT 11 1995

FARMINGTON DISTRICT OFFICE
BY [Signature]

AMCOB