## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	API	# (assign		<b>)</b>
. Type of Well	5.	30-039-2 <b>Lease Nu</b>		
GAS	6	Fee	100 7	#
	6.	State O1	l&Gas Lea	lse #
. Name of Operator	7.	Lease Na	me/Unit N	lame
BURLINGTON			20 7 17-1	_
RESOURCES OIL & GAS COMPANY	8.	Well No.	29-7 Uni	. L
. Address & Phone No. of Operator	2	73A		
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Pool Nam Blanco M	<b>le or Wilc</b> Mesaverde	icat
. Location of Well, Footage, Sec., T, R, M		Elevation		
790'FNL, 1660'FWL, Sec.24, T-29-N, R-7-W, NMPM, Rio Arril	ba County			
Type of Submission Type of Action		-		
Notice of Intent Abandonment Character Net	ange of Pl w Construc	LIOH		
X Subsequent Report Plugging Back No.	n-Routine	Fracturin	g	
Casing Repair Wa	iter Shut o	ff o Iniecti	on	
Final Abandonment Altering Casing Co	/	0 111,000		
X Other - Spinner survey				
3. Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over	c existing	peris. TO	OH.	
3. Describe Proposed or Completed Operations 2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO	c existing	peris. TO	OH. P. NU WH.	
3. Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	c existing	peris. TO 6'. ND BOI	OH. P. NU WH.	
3. Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	existing nded @ 546	peris. TO 6'. ND BOI	OH. P. NU WH.	
Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	ECEING  MAR - 2 1	Peris. TO 6'. ND BOI	OH. P. NU WH.	
3. Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	existing nded @ 546	Peris. TO 6'. ND BOI	OH. P. NU WH.	
Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	ECEIN  MAR - 2 1	Peris. TO 6'. ND BOI	OH. P. NU WH.	
3. Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	ECEIN  MAR - 2 1  L CON.  DIST. 3	Peris. TO 6'. ND BOI 999 DIV.	P. NU WH.	
Describe Proposed or Completed Operations  2-25-99 MIRU. ND WH. NU BOP. TIH to PBTD @ 5675'. TO 2-26-99 TIH w/spinner tools. Run spinner survey over TIH w/174 jts 2 3/8" 4.7# J-55 EUE tbg, lar RD. Rig releeased.	ECEIN  MAR - 2 1  L CON.  DIST. 3	Peris. TO 6'. ND BOI 999 DIV.	P. NU WH.	