

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

January 21, 1966

Tenneco Oil Company
P.O. Box 1714
Durango, Colorado 81302

Attn: Mr. J.E. Massey
District Production Engineer

Dear Mr. Massey:

The packer leakage test which was submitted January 3, 1966 for your #3 Pritchard well located in Unit N, Section 31-29N-8W indicates the probability of communication between the producing zones. You are, therefore, directed to take immediate remedial action to effectively separate the producing zones in this well.

If you wish to conduct further tests to attempt to prove separation prior to commencing remedial work, please contact us prior to conducting additional tests.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

cc: OCC, Santa Fe, N.M.
USGS, Farmington, N.M.

