UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS SF-078414 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. ndian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation 1. Type of Well Gas Well Oil Well Other 8. Well Name and No. 2. Name of Operator Day B 3 Attention: **Amoco Production Company** 9. API Well No. Lois Raeburn 3. Address and Telephone No. 3004508584 (303) 830-5294 P.O. Box 800, Denver, Colorado 80201 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Mesaverde 11. County or Parish, State 979'FNL 1639'Fel Sec. 8 T 29N R 8W San Juan New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans Notice of Intent Recompletion **New Construction** Plugging Back Non-Routine Fracturing Subsequent Report Casino Repair Water Shut-Off Altering Casing Conversion to Injection Final Abandonment Notice Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Amoco Production Company request permission to Plug & Abandon subject well. 14. I hereby certify than the foregoing is true and correct 07-28-1995 Staff Assistant (This space for Federal or State office use) Title Approved by Conditions of approval, if any:

FORM APPROVED

Budget Bureau No. 1004-0135 Expires: March 31, 1993

* See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States

representations as to any matter within its jurisdiction.

SJOET Well Work Procedure

Day B #3

Version:

#1

Date:

July 27, 1995

Budget: Repair Type: DRA PXA

Objectives:

•

1. To PXA the entire well

Reason: Unable to produce in paying quantities.

Pertinent Information:

Location:

979 FNL 1639 FEL Sec 8 T 29N R 8W

Horizon:

MV

County:

San Juan New Mexico

978651

API #: Engr: 300450858400 Wyett/Kolodzie

State: Lease:

Well Flac:

BLM NMSF-047039A

Phone:

H--(303)-368-7795

W-(303)-830-5578 P--(303)

Economic Information:

APC WI:

.50

Estimated Cost:

\$22,000.00

Formation Tops: (Estimated formation tops)

Nacimento:

Menefee:

4918

Ojo Alamo:

Kirtland Shale:

Point Lookout:

Fruitland:

2196 2814 Mancos Shale:

Pictured Cliffs:

3134

Gallup: Graneros:

Lewis Shale:

3224

Dakota:

Cliff House:

4726

Morrison:

Bradenhead Test Information:

BH

Test Date:

6/8/87

380

Casing: 380

BH: 0

Time

CSG

Tubing:

INT

CSG

5 min

10 min

15 min

Comments:

Day B #3
Orig. Comp. 12/52
TD = 5533', PBTD = Open hole
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. RIH with tbg and CIBP. Set CIBP at 4630'. Test casing integrity to 500#. Run short string CBL. Spot a cement plug on top to 3100' with 139 cuft cement. RIH with perf gun and shoot squeeze holes at TOC and circulate to surface. Pull out and spot cement plug to surface. (Estimate from CIBP to surface 696 cuft)
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

DAY B 003
Location — 8B— 29N— 8W
SINGLE mv
Orlg.Completion — 12/52
Last File Update — 1/89 by BCB

