Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OMB/NO. 1004-0135
Expires: November 30, 200

5.	Lease Serial No.
	Lease Serial No. NMSF / 078046

Do not use thi abandoned wei	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	PLICATE - Other instruction	ns on reverse slidel	3 14 15 16	7. If Unit or CA/A	greement, Name and/or No.		
Type of Well Oil Well	JUN	2002	8. Well Name and N HUGHES LS 1				
Name of Operator BP AMERICA PRODUCTION	RY (WRLEY R . C.		9. API Well No. 30-045-21037				
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	b. Phone No. (include and h: 28 (366.449) x: 281.366.0700	r code)	10. Field and Pool, or Exploratory BLANCO PICTURED CLIFFS				
4. Location of Well (Footage, Sec., 7	LEE 82	8717 87 January 198	11. County or Parish, and State				
Sec 20 T29N R8W NWNE 10		SAN JUAN COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	NDICATE NATURE	E OF NOTICE, R	EPORT, OR OTH	IER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent	☐ Acidize	□ Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclan	nation	☐ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	□ New Constructi	on 🔲 Recom	plete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Aband	lon 🔲 Tempo	rarily Abandon			
<u> </u>	☐ Convert to Injection	☐ Plug Back	☐ Water 1	Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Please reference telephone conversation on May 17, 2002, between representatives of BP America and Steve Mason, BLM and Charlie Perrin, NMOCD, regarding bringing various inactive wells into compliance. The subject well was approved for plug and abandonment on 03/14/2000. Verbal permission was granted to temporarily abandon the well (i.e. pressure test for casing integrity) in order to bring well into compliance and hold for possible production stimulation in the current zone or recompletion into the Fruitland Coal Formation. If the casing integrity test fails we will proceed immediately with plug and abandonment operations as per previously approved procedure. Please note we conducted a casing integrity test as follows for the subject well on 5/24/2002, however, the casing integrity failed. We therefore request permission to plug and abandon the well bore per procedures following test data.							
14. I hereby certify that the foregoing is Name (Printed/Typed) MARY CO	Electronic Submission #116 For BP AMERICA PROD Committed to AFMSS for	UCTION COMPANY, r processing by Steve	sent to the Farmir	igton 2002 ()			
Name (Times Types) WART COREET			3		· · · · · · · · · · · · · · · · · · ·		
Signature (Electronic S	Submission)	Date 05	5/30/2002				
	THIS SPACE FOR	FEDERAL OR ST	ATE OFFICE U	SE			
Approved By		Title		Dat	e 6/12/02		
Conditions of approval, if any, are attache ertify that the applicant holds legal or equicing would entitle the applicant to conditions.	uitable title to those rights in the su						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a cristatements or representations as to	me for any person knowir	ngly and willfully to rediction.	nake to any departmer	at or agency of the United		

Additional data for EC transaction #11619 that would not fit on the form

32. Additional remarks, continued

05/24/2002 RU slickline unit. RIH & set plug @ 3025'. Loaded well with 2% KCL. Pressure tested casing. Casing failed to pressure test. Casing leak located @ 1700'. Pull plug. RD slickline unit.

PROPOSED P&A PROCEDURE.

1. MIRU workover rig

1. MIRU workover rig
2. RIH w/CIBP & set @ 3025'. Spot 300' CMT on top of CIBP to cover the Pictured Cliffs, Fruitland
Coal A 673 At 1674. To 1934'
3. RIH w/CMT retainer & set @ 1650'. Sting into retainer & SQZ CSG leak w/8 sacks CMT. Spot 100'
CMT plug above retainer.
4. Perforate SQZ holes at 300'. 702'
F. Pump CMT down CSG & circulate CMT to surface. Leave CSG full w/CMT to surface.

5. Pump CMT down CSG & circulate CMT to surface. Leave CSG full w/CMT to surface. 6. Cut off wellhead & install P&A marker.

7. RDMO workover rig

8. Rehabilitate location according to BLM or State requirements.