

& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6176 FAX: (505) 334-6170 http://www.rdc.division.com/collection/

This form is not to be used for reporting packer leakage tests in Southeast New Mexico

Page 1 Revised 11/16/98

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

	bp America 200 Energy			me	inderw	art A	Well No_UA	
Location of	Well:Unit Letter	r <u> </u>	11 Twp 20	<u> N</u> Rge_ <u> </u>	<u>W</u> API#	30-0 <u>¹45-∂</u>	2361	
	NAME OF RESE		TYPE OF PROD. (Oil or Gas)		D OF PROD. or Art. Lift)	PROD.MEDIUM (Tbg. or Csg.)		
Upper Completion	Blanco	GA	GAS		LOW	TBG		
Lower Completion	Blanco	GA	GAS		LOW	TBG		
		PRE	-FLOW SHUT-I	N PRESSUI	RE DATA			
Upper	Hour, date shut-in		1	Length of time shut-in		9	Stabilized? (Yes or No)	
Completion	Hour, date shut-in	<u>/oə</u>		72 HOURS		19	YES	
Lower Completion	6/2	/ /		URS	SI press. Psi		Stabilized? (Yes or No) YES	
			FLOW TE	ST NO. 1				
Commenced at (hour, date)*			Zone producin	g (Upper or Low	er):		
TIME (hour,date)	LAPSED TIME SINCE*			PROD. ZON TEMP.		E REMARKS		
			SSURE		ŧΕ	R	EMARKS	
(hour,date)	SINCE*	Upper Completion	Lower Completion		łE	R	EMARKS	
(hour,date)		Upper Completion	Lower Completion			H ZONES SI		
(hour,date)	DAY 1 DAY 2	Upper Completion	Lower Completion		ВОТ		UT IN	
(hour,date)	SINCE*	Upper Completion	Lower Completion		B07 B07	H ZONES SI	HUT IN	
(hour,date) 6 / 25 6 / 26	DAY 1 DAY 2	Upper Completion	Lower Completion		B07 B07	H ZONES SE H ZONES SE H ZONES SE	HUT IN	
(hour,date) 6 / 25 6 / 26 6 / 27	DAY 1 DAY 2 DAY 3	Upper Completion 214 217 217	Lower Completion 141 142 143 144		BOT BOT	H ZONES SH H ZONES SH H ZONES SH W () pper	HUT IN HUT IN	
(hour,date) 6 / 25 6 / 26 5 / 27 6 / 28	DAY 1 DAY 2 DAY 3 DAY 4	Upper Completion 214 217 217 219 1109	Lower Completion 141 142 144 143		BOT BOT FLO	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE	
(hour,date) 6 / 25 6 / 26 5 / 27 6 / 28 6 / 29	DAY 1 DAY 2 DAY 3 DAY 4 DAY 5 DAY 6	214 217 217 219 169	Lower Completion 141 142 143 144		BOT BOT BOT FLO	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE ZONE	
(hour,date) 6 / 25 6 / 26 5 / 27 6 / 28 6 / 29 6 / 30	DAY 1 DAY 2 DAY 3 DAY 4 DAY 5 DAY 6	214 217 217 219 169	Lower Completion 141 142 144 143 144	TEMP.	BOT BOT FLO FLO	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE ZONE	
(hour,date) 6 / 25 6 / 26 5 / 27 6 / 28 6 / 29 6 / 30 Production rate	DAY 1 DAY 2 DAY 3 DAY 4 DAY 5 DAY 6	Upper Completion 214 217 219 169 156 146 BOPD based	Lower Completion 141 142 144 143 144	Bbls. in	BOT BOT FLO FLO FLO	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE ZONE ZONE	
(hour,date) 6 / 25 6 / 26 6 / 27 6 / 28 6 / 29 6 / 30 Production rat	DAY 1 DAY 2 DAY 3 DAY 4 DAY 5 DAY 6	Upper Completion 214 217 219 169 156 146 BOPD based	Lower Completion 141 142 144 144 144 144 10n PD; Tested thru	Bbls. in (Orifice or M	BOT BOT FLO FLO FLO Hours	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE ZONE ZONE	
(hour,date) 6 / 25 6 / 26 6 / 27 6 / 28 6 / 29 6 / 30 Production rat	DAY 1 DAY 2 DAY 3 DAY 4 DAY 5 DAY 6	Upper Completion 214 217 219 169 156 146 BOPD based	Lower Completion 141 142 144 143 144 144	Bbls. in (Orifice or M	BOT BOT FLO FLO FLO Hours	H ZONES SH H ZONES SH H ZONES SH W () pper W "	HUT IN HUT IN HUT IN ZONE ZONE ZONE	

(Continue on reverse side)

New

FLOW TEST NO. 2

Zone producing (Upper or Lowr):

TIME (hour,date)	LAPSED TIME Since**	PRESS Upper Completion	SURE Lower Completion	PROD. ZONE	REMARKS
		PC	mv		
9/10		.158	116		Both Zones Shut In
9/11		183	139		
9/12		207	143		1 1 1 1
9/13		210	106		From Lower Zone
9/14		<u>a13</u>	86		
9/15		215	85		T T T
Production rat	e during test				
Dil:	BOPD I	pased on	Bbls.	inHours	GravGOR
3as:		МСЕР	'D: I ested thru (O	ffice or Meter):	
Remarks:			· · · · · · · · · · · · · · · · · · ·	·	<u> </u>
hereby certify	that the inform	ation herein con	tained is true and	complete to the t	pes of my knowledge.

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

Operator_

Date

1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.

EAS IMPLECT

19

Commenced at (hour, date)**

Approved

Title

Mexico Oil Conservation Division

- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the weilhead pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial

packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.

- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test no. 2 is to be the same as for Flow Test No. 1 except

that the previously produced zone shall remain shut-in while the zone which wa previously shut-in is produced.

Amoco Production Company

Sheri Bradshaw

7. Pressures for gas-zone tests must be measured on each zone with a deadweigh pressure gauge at time intervals as follows: 3 hours tests: immediately prior to th beginning of each flow-period, at lifteen-minute intervals during the first hour thereo and at hourly intervals thereafter, including one pressure measurement immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested of wells which have previously shown questionable test date.

24-hour oil zone tests: all pressures, throughout the entire test, shall b continuously measured and recorded with recording pressure gauges the accurac of which must be checked at least twice, once at the beginning and once at the endered test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gadual completion, the recording gauge shall be required on the oil zone only, will deadweight pressures as required above being taken on the gas zone.

8. The result's of the above-described tests shall be filed in triplicate within 15 day after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico oil Conservation Division on northwest new Mexico packer leakage. Tes Form Revised 11-16-98 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only), and gravity and GOR (oil zones only).