## **UNITED STATES DEPARTMENT OF THE INTERIOR**

FORM APPROVED		
Budget Bureau No. 1004-0135		
Expires: March 31, 1993		

BUREAU OF LAND MAN	VAGEMENT	Expires: March 31, 1993
SUNDRY NOTICES AND REP  Do not use this form for proposals to drill or to deepen  Use "APPLICATION FOR PERMIT - "	or reentry to a different reservoir.	Lease Designation and Serial No.     SF-078415      B. If Indian, Allottee or Tribe Name
1. Type of Weil		7. If Unit or CA, Agreement Designation
Weil   Gas  Weil   Other	•	8. Well Name and No.
2. Name of Operator	Attention:	Roelofs B #3A
AMOCO PRODUCTION COMPANY  3. Address and Telephone No.	Gail M. Jefferson	9. API Well No.
P.O. BOX 800 DENVER, COLORADO 80201	(303) 830-6157	3004522365 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde/Pictured Cliffs
1060' FNL 880' FWL Sec. 15	5 T 29N R 8W UNIT D	11. County or Parish, State  SAN JUAN NEW MEXICO
12. CHECK APPROPRIATE BOX(s) TO II	NDICATE NATURE OF NOTICE RE	
TYPE OF SUBMISSION	TYPE OF ACTION	FORT, OR OTHER DATA
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Attering Casing Other Downhole Commingle (Note: Report r	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water  esults of multiple completion on Well Completion or Recompletion Report and Log form.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc markers and zones pertinent to this work.)*  Amoco Production Company requests permission If you have any technical questions please contact concerns.	to downhole commingle this well per the a	ttached procedures.
4. I hereby certify that the foregoing is true and correct Signed Lack Cul. Helesan his space for Federal or State office use)	Title Sr. Admin. Staff	Asst. Date 01-15-1999
Approved by Conditions of approval, if any:	Title	Date 1/29/99
. 3 18 U.S.C. Section 1001, makes it a crime for any person knowingly and walfully to make to any department	or agency of the United States any false, ficticious, or fraudulent statements or rep	presentations as to any matter within its jurisdiction.

\* See Instructions on Reverse Side

Meed DH Corder E

NMOCD

## Roelofs B #3A TD = 5595' PBTD = 5578' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. TOOH with 1 1/4" tubing set @ 3042'.
- 6. Pressure test 2-3/8" tbg.and 7" csg. to check for potential leaks.
- 7. Unseat and TOOH with 2 3/8" tubing set @ 5515'. Model D packer @ 3090'.
- 8. DO Model D Packer (7") @ 3090' using air.
- 9. CO to PBTD; pressure test 4.5" liner to 1000#.
- 10. TIH with 2 3/8" tubing and set @ 5400'.
- 11. Return commingled (PC + MV) well to production; set plunger and alter criteria if necessary.

ROELOFS LS 003A 1727
Location — 15D—29N—8W
DUAL PC—MV
Orig.Completion — 9/77
Last File Update — 1/89 by DDM

