

December 14, 1990

Oil Conservation Division  
ATTN: Dorothy Jacquez  
1000 Rio Brazos Road  
Aztec, NM 87410

Dear Ms. Jacquez:

In filing of the Sundry Notices with the BLM, the pressure testing of the casing strings were inadvertently left off the notices. All future Sundry Notices will have the pressure testing information included. The following wells have the pressure information missing from the Sundry Notices:

Well #14 Day B  
Lease #SF-078414  
NE/4 Sec. 8-T29N-R8WWell #4 Roelofs A  
Lease #SF-078415  
NE/4 Sec. 9-T29N-R8WWell #8 Roelofs B  
Lease #SF-078415  
NE/4 Sec. 22-T29N-R8WWell #13 Vandewart A  
Lease #SF-078502  
SW/4 Sec. 13-T29N-R8WWell #14 Vandewart A  
Lease #SF-078502  
NE/4 Sec. 14-T29N-R8W**Well #7 Roelofs B**  
Lease #SF-078415  
SW/4 Sec. 15-T29N-R8WWell #18 Hughes B  
Lease #SF-078046  
NE/4 Sec. 21-T29N-R8WWell #11 Wilch A  
Lease #SF-078416A  
NE/4 Sec. 23-T29N-R8WWell #12 Wilch A  
Lease # SF-078416  
SW/4 Sec. 23-T29N-R8WWell #19 Hughes B  
Lease #SF-078046  
NE/4 Sec. 29-T29N-R8W

The pressure testing information is the same for the above wells. The surface casings (8 5/8") were tested to 1000 psi. for ten minutes and held. The production casings (5 1/2") were tested to 2600 psi. for 30 minutes and held.

I have attached nine copies of this letter one for each well folder. The well we are trying to expedite is the Roelofs B #7. If you have any questions or need additional information do not hesitate to give me a call at (405) 948-3234.

*Gregory M. Gazda*Gregory M. Gazda  
Staff Engineer, P.E.

GMG/083.wpd/sh

**RECEIVED**  
DEC 26 1990  
OIL CON. DIV.  
DIST. 3