

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. Simmons - P.C. No. 9 SF 080245-B	
2. NAME OF OPERATOR D. J. Simmons, et al		6. IF INDIAN, ALIEN, OR TRIBE NAME	
3. XXXXXXXXXXXX 1760' from North line, 1680' from West line, Sec. 21 - T29N - R9W., San Juan Co., N.M.		7. UNIT AGREEMENT NAME	
4. XXXXXXXXXX WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Address of Operator: 3815 McCart Street - Fort Worth, Texas 76110		8. FARM OR LEASE NAME Simmons	
14. PERMIT NO.		9. WELL NO. No. 9	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5624 K.B.		10. FIELD AND POOL, OR WILDCAT Blanco - P.C.	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21 - T29N - R9W. N.M.P.M.	
		12. COUNTY OR PARISH San Juan	
		13. STATE N.H.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed that the above captioned well be abandoned in the following manner:

1. Place a cement plug from the Plugback T.D. of 2192' up to 2000' to cover perforations (2082' - 2159').

2. Place a cement plug from approx. base of Ojo Alamo at 1100' up to 1050' in 4 1/2" pipe.

3. Perforate at approximate 700' below well head and pump cement to kill water flow.

4. Leave minimum of 50' plug in 4 1/2" casing opposite surface casing shoe.

5. Install surface marker and clear location as required.

6. It is estimated that work will be completed within 90 days of the present date (October 29, 1974). Plugging agent will be notified immediately to commence this operation at his earliest available time.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ashton B. Geren, Jr.
Ashton B. Geren, Jr.

TITLE

Supt.-Manager for
B.J. Simmons, et al

U. S. GEOLOGICAL SURVEY

DATE **October 29, 1974**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.