

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-23724
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Chavez Gas Com D
8. Well No. 1E
9. Pool name or Wildcat Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Amoco Production Company Attn: John Hampton	
3. Address of Operator P.O. Box 800 Denver, Colorado 80201	
4. Well Location Unit Letter <u>J</u> : <u>1560</u> Feet From The <u>South</u> Line and <u>1760</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>29N</u> Range <u>9W</u> NMPM <u>San Juan</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: OIL CON. DIV. /

OTHER: Test casing and acidize

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company performed the following work on the subject well.

1. TOH 108 stand 2 3/8" tbg. No fill. Replaced offside csg valve.
2. Set RBP @ ±6300'. Pulled up 1 jt & set pkr. Pr tst RBP to 200# for 10 min. Pr tst backside pkr to 1000 for 20 min. Held. No casing leak found.
3. Remove pkr. Ran CBL 4700' to 2650'. Retrieve BP.
4. Land 2 3/8" tbg @ 6961'.
5. Acidized well with 25 BBL 7.5% acid. Waited 15 min. Flushed with 30 BBL 2% KCL.
6. Returned to production.

Please call Cindy Burton at 303-830-5119 if you have any questions.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

John L. Hampton

TITLE

Sr. Staff Admin. Supv.

DATE

10/24/90

TYPE OR PRINT NAME

John L. Hampton

TELEPHONE NO.

830-5025

(This space for State Use)

Original Signed by FRANK T. CHAVEZ

APPROVED BY

TITLE

SUPERVISOR DISTRICT # 3

DATE

OCT 29 1990

CONDITIONS OF APPROVAL, IF ANY: